

DEVELOPMENT OF SILICON NITRIDE OF IMPROVED TOUGHNESS

by/J.J./Brennan

October 2, 1979

UNITED TECHNOLOGIES RESEARCH CENTER

prepared for NATIONAL AERONAUTICS AND SPACE ADMINISTRATION

NASA Lewis Research Center Contract NAS3-21375

FINAL REPORT

REPRODUCED BY
NATIONAL TECHNICAL
INFORMATION SERVICE
U.S. DEPARTMENT OF COMMERCE
SPRINGFIELD, VA. 22161

NOTICE

THIS DOCUMENT HAS BEEN REPRODUCED FROM THE BEST COPY FURNISHED US BY THE SPONSORING AGENCY. ALTHOUGH IT IS RECOGNIZED THAT CERTAIN PORTIONS ARE ILLEGIBLE, IT IS BEING RELEASED IN THE INTEREST OF MAKING AVAILABLE AS MUCH INFORMATION AS POSSIBLE.

1	Report No.	2 Gaussana Assaul	ia- Na	2 Parinipatio Catalon	N-								
	NASA CR-159676	2. Government Access	ion No.	3. Recipient's Catalog	Catalog No.								
4.	Title and Subtitle			5. Report Date									
				October 2, 1979									
	DEVELOPMENT OF SILICON NITRIDE O	OF IMPROVED TOUGH	NESS	6. Performing Organization Code									
7.	Author(s)			8. Performing Organiz	ation Report No.								
	J. J. Brennan			R79-914364-12	9-914364-12								
	3. 5. Breiman			10. Work Unit No.									
9.	Performing Organization Name and Address												
	United Technologies Research Cer	ter		11. Contract or Grant No.									
	East Hartford, CT 06108			NAS 3-21375									
			13. Type of Report and Period Covered										
12.	Sponsoring Agency Name and Address												
	National Aeronautics and Space A	dministration		Contractor Re									
	Washington, DC 20546			14. Sponsoring Agency	Code								
15													
13.	5. Supplementary Notes Final Papart - Project Manager William A. Candena NASA Levie Research Contan and												
	Final Report - Project Manager, William A. Sanders, NASA-Lewis Research Center and Propulsion Laboratory, U.S. Army Research & Technology Laboratories												
1	Cleveland, OH 44135												
16	Austract	-11			77								
	The application of reaction sint	tered Si ₃ N ₄ energ	y absorbing surface	layers to hot-pr	, , ,								
	investigated. The surface layer												
	that reaction sintered Si ₃ N ₄ lay												
	-325 mesh Si powder and aitrided	in 96% N ₂ /4% H ₂	so that ~20-25 vol	% unnitrided Si	remained in the								
	layer, resulted in a sevenfold in	increase in balli	stic impact resistan	ce of a 0.64 cm	thick hot-								
	pressed Si ₃ N ₄ substrate from RT												
	with $Y_2O_3^{-1}$ additive, were evaluate nitrided Si layers were found to												
	It was found that nitriding in N_2/H_2 mixtures, rather than pure N_2 , resulted in a microstructure that did not substantially degrade the strength of the hot-pressed Si_3N_4 substrate.												
				1	(-								
	Thermal cycling tests on the RSS not degrade the impact resistant												
	silica formation occurred within the RSSN layer. Mach 0.8, 5 hr, hot gas erosion tests showed no surface recession of RSSN layers at 1200°C and slight surface recession at 1370°C.												
					15-117-52								
	The formation of an oxidation and erosion protective CVD $\mathrm{Si}_3\mathrm{N}_4$ overlayer on the RSSN layers was not												
	successful due to interaction between the residual Si and the deposition process. CVD SiC over-												
	layers were successfully fabricated and, while not optimized, showed excellent thermal cycling and hot gas erosion resistance.												
	•												
	In addition, a brief study was			blem in the temp	erature range								
	700-1000 °C of the NCX-34 Si ₃ N ₄	(Y_2O_3) material u	sed in this program.										
17	Kay Words (Suggested by Author(s))		10 Distribution Statement										
1/.	Key Words (Suggested by Author(s))		18. Distribution Statement										
	Ceramics for Gas Turbines												
	Silicon Nitride Impact Resistand	ce Improvement	Unclassified - U	nlimited									
	Energy Absorbing Surface Layers Silicon Nitride Ballistic Impact	Properties											
	officen afteride parristic impact	roper crea											
19.	Security Classif. (of this report)	20. Security Classif. (c	of this page)	21. No. of Pages	22. Price*								
	Unclassified	Unclassified		107									

Development of Silicon Nitride of Improved Toughness

TABLE OF CONTENTS

Ι.	INTRO	ODUCTION	N		٠.	•			•						•		•	•								1
II.	BACK	GROUND .																								2
III.	SUMM	ARY .							•																	4
IV.	TECHNICAL PROGRESS SUMMARY														8											
	4.1	Fabrica 4.1.1																						•	•	8
		4.1.2	Si ₃ N ₄ Fabri																		•	•	•	•	•	8
			Combi	nat	ions																					10
	4.2	Ballis	tic Im	pac	t Te	sti	ng																			11
		4.2.1	Balli	stí	c Im	pac	t '	Tes	ti	ng	of	S	L ₃ N	14 (Con	tt	co I	s								12
	4.3	4-Pt Be	end Te	sti	ng o	f N	CX	-34	ar	nd	NC	-13	32	Si	N	. (Cor	ıtr	01	s						12
	4.4	Task I - Development of RSSN Energy Absorbing Surface																								
		Layers																								13
		4.4.1	Balli	sti	e Im	pac	ct	Tes	tir	ng	of	R	SSN	/H1	PSN	(Con	nbi	na	ti	on	ıs				13
			4.4.1																							
					Gra	ine	d	RSS	N I	Lay	er	s														15
			4.4.1	. 2																						
					Gra	ine	ed	RSS	N I	Lay	er	s														18
			4.4.1	.3	Bal	lis	ti	c I	mpa	act	: 0	bse	erv	at:	Lon	s										19
		4.4.2	4-Pt						_																	20
			4.4.2	.1	Ben	d 7	les	t o	f	RSS	SN/	HPS	SN	Cor	ıbi	na	ati	on	s	Ni	tr	cic	led	i		
					in	a N	12/1	H_2	Mia	ktı	ıre															22
			4.4.2	. 2	Con																					
					Ben	d S	str	eng	t.h																	23
		4.4.3	Task	I -				_																		24
	4.5	Task II																								
		With an								-																24
		4.5.1					-						-	•												24
		4.5.2	Therm																							25
		4.5.3	Therm	al (Cyc1	ing	3 0	f R	SSI	N/H	IPS	N (Con	bir	at	ic	ns	W	it	h						
			CVD S	iaN	or	Si	C	Ove	rla	aye	ers															26

TABLE OF CONTENTS (Cont'd)

4		Mach 4.5.4 4.5.4	4.1	Ero	sion	Te	stir	ng o	f Si	3N4	Cor	tro	1s				28 28 29
		4.5.4	4.3				stir SiC										29
v. conclu	SIONS																32
REFERENCES																	35
TABLES I -	XXIII.																37
FIGURES 1 -	. 48																

I. INTRODUCTION

The application of refractory ceramic materials, in particular $\mathrm{Si}_3\mathrm{N}_4$ and SiC , for use in advanced gas turbine engines has recently been an extremely active area of interest. Both $\mathrm{Si}_3\mathrm{N}_4$ and SiC have exhibited excellent properties in the areas of strength, thermal shock, creep resistance, and oxidation resistance. However, the use of these materials in certain critical gas turbine applications may be severely limited due to their very low fracture toughness (i.e., resistance to impact damage). Thus, it is imperative to improve the toughness of these materials without sacrificing or compromising their good mechanical and thermal properties.

Various research programs having the objective of improving the impact resistance of $\mathrm{Si}_3\mathrm{N}_4$ and SiC have been completed during the last few years. These programs were based on three general approaches:

- (1) Improving the impact resistance by fiber reinforcement (Refs. 1-3).
- (2) Improving the strength and impact resistance by compressive surface layers (Refs. 4-6,10).
- (3) Improving the impact resistance by energy absorbing surface layers (Refs. 1,7-10).

The first of these approaches was previously studied at United Technologies Research Center with excellent results for improving the impact resistance of hot-pressed $\mathrm{Si}_3\mathrm{N}_4$ through the use of tantalum wire reinforcement. The second and, in particular, the third of these approaches was studied in a recent NASA contract NAS3-19731 (Ref. 10), the highlights of which are given in the following section of this report. From the results of this previous work, it was decided to concentrate efforts in the current contract on improving the impact resistance of hot-pressed $\mathrm{Si}_3\mathrm{N}_4$ through the use of energy absorbing surface layers of porous reaction sintered $\mathrm{Si}_3\mathrm{N}_4$.

The objective of this program is to improve the toughness of $\mathrm{Si}_3\mathrm{N}_4$ by the development and control of the process of formation of an energy absorbing $\mathrm{Si}_3\mathrm{N}_4$ surface layer on a dense $\mathrm{Si}_3\mathrm{N}_4$ substrate by in-place nitridation of silicon powder. The program is divided into two tasks:

- Task I Development of Reaction Sintered Si₃N₄ (RSSN) Energy Absorbing Surface Layers on Hot-Pressed Si₃N₄
- Task II Effect of Thermal Exposures on R.S. Si_3N_4 H.P. Si_3N_4 Combinations With and Without Overlayers of Chemically Vapor-Deposited (CVD) Si_3N_4 .

II. BACKGROUND

The use of energy absorbing surface layers of porous $\mathrm{Si}_3\mathrm{N}_4$ on dense hotpressed $\mathrm{Si}_3\mathrm{N}_4$ in order to improve impact resistance was first studied under the recently completed contract NAS3-19731 (Ref. 10). It was anticipated that surface layers of this type could be expected to absorb energy upon impact due to crushing and crack diversion.

Charpy and ballistic impact specimens of R.S. $\mathrm{Si}_3\mathrm{N}_4$ layers on NC-132 $\mathrm{Si}_3\mathrm{N}_4$ were fabricated in situ by nitriding a layer of silicon metal powder that had been applied using a water or toluene based slurry. The types of R.S. $\mathrm{Si}_3\mathrm{N}_4$ surface layers investigated varied from relatively dense (70%), fine-grained R.S. $\mathrm{Si}_3\mathrm{N}_4$ made from -325 mesh Si powder to quite porous (55% dense), large particle-sized layers made from -100, +200 mesh Si powder.

The results of Charpy impact tests at RT and 1370°C showed that the nitrided -200 Si and -325 Si layers on NC-132 Si $_3\text{N}_4$ did not increase the Charpy impact resistance significantly over Si $_3\text{N}_4$ control values. In contrast to the nitrided -325 Si and -200 Si layers, however, the higher porosity large grain size nitrided -100, +200 Si layers on NC-132 Si $_3\text{N}_4$ exhibited Charpy impact energies $2^{\frac{1}{2}}$ times NC-132 Si $_3\text{N}_4$ controls at RT and slightly over twice that recorded for $5i_3\text{N}_4$ controls at 1370°C . From the instrumented Charpy impact load vs time curve it was evident that crushing of the R.S. Si $_3\text{N}_4$ layer occurred during impact.

Ballistic impact tests at RT and 1370°C of R.S. $\text{Si}_{3}\text{N}_{4}$ layers on NC-132 $\text{Si}_{3}\text{N}_{4}$ resulted in a fivefold to sixfold improvement in impact energy before substrate failure for nitrided -100, +200 Si and -200 Si layers but only a two to threefold improvement for nitrided -325 Si layers over NC-132 Si₃N₄ control values. To realize optimum energy absorption during a ballistic impact event, it was thought that a combination of porosity and fairly large particle size was necessary to allow crushing of the R.S. $\text{Si}_{3}\text{N}_{4}$ layer but at the same time, be somewhat resistant to penetration by the projectile.

In order to evaluate the effect of the R.S. $\rm Si_3N_4$ energy absorbing surface layers on the strength of the NC-132 $\rm Si_3N_4$ when the interface between the R.S. $\rm Si_3N_4$ and NC-132 $\rm Si_3N_4$ is subjected to tensile (bending) stresses, a series of Charpy impact tests were performed with the samples impacted on the side opposite the R.S. $\rm Si_3N_4$ layer. The results of these tests showed that well bonded R.S. $\rm Si_3N_4$ layers degraded the Charpy impact strength and bend strength of the NC-132 $\rm Si_3N_4$ by up to 50%. In general, the large particle and pore size nitrided -100, +200 Si layers degraded the strength more than the smaller particle and pore size nitrided -325 Si layers. The possibility that the degradation is due to the large pores in the R.S. $\rm Si_3N_4$ layer near the interface acting as stress concentrating flaws suggested that minimizing pore size at the R.S. $\rm Si_3N_4$ (H.P. $\rm Si_3N_4$ interface by using a graded density R.S. $\rm Si_3N_4$ layer could possibly help alleviate this problem.

Thermal cycling of R.S. $\mathrm{Si}_3\mathrm{N}_4$ surface layers on NC-132 $\mathrm{Si}_3\mathrm{N}_4$ between $200^\circ\mathrm{C}$ and $1370^\circ\mathrm{C}$ in air for up to 50 cycles resulted in a large amount of silica formation in the high surface area nitrided -325 Si layers that caused debonding at the R.S. $\mathrm{Si}_3\mathrm{N}_4/\mathrm{H.P.}$ Si $_3\mathrm{N}_4$ interface possibly due to thermal expansion mismatch between the silica and the NC-132 $\mathrm{Si}_3\mathrm{N}_4$. The larger particle size nitrided -100, +200 Si layers did not form sufficient silica to cause debonding during thermal cycling with the result that the ballistic impact resistance of these cycled layers was the same as noncycled layers at RT and mugh higher at $1370^\circ\mathrm{C}$. The increase at elevated temperature may be due to plastic deformation of the silica during the high temperature ballistic impact event. For a practical R.S. $\mathrm{Si}_3\mathrm{N}_4$ energy absorbing surface layer that must operate in a gas turbine environment, it may be necessary to have an outer layer of dense, impermeable CVD $\mathrm{Si}_3\mathrm{N}_4$ covering the R.S. $\mathrm{Si}_3\mathrm{N}_4$ surface to add oxidation and possibly erosion resistance.

III. SUMMARY

The development of $\mathrm{Si}_3\mathrm{N}_4$ of improved toughness was accomplished by the investigation of reaction sintered $\mathrm{Si}_3\mathrm{N}_4$ (RSSN) energy absorbing surface layers on hot-pressed $\mathrm{Si}_3\mathrm{N}_4$ (HPSN) by in-place nitridation of silicon powder. Two types of HPSN substrates were used, NC-132 $\mathrm{Si}_3\mathrm{N}_4$ with MgO additive and NCX-34 $\mathrm{Si}_3\mathrm{N}_4$ with $\mathrm{Y}_2\mathrm{O}_3$ additive. Three different particle size Si powders were evaluated: -100, +200 mesh, -200 mesh, and -325 mesh. The toughness increase due to the presence of the 1 mm thick RSSN layers was measured through the use of a ballistic impact test at RT and 1370 °C. The effect of the RSSN layer on the strength of the HPSN substrate was measured at RT through the use of a 4-pt bend test with the RSSN layer on the tensile side of the sample.

During characterization of the NCX-34 Si₃N₄ it was found that this particular lot of material undergoes excessive oxidation and resultant loss in strength after 48 hrs at 700-1000 C in air even though NCX-34 material studied previously was very good in low temperature oxidation. It was also found that this lot of material contained 7.15 w/o Y (9.1 w/o Y₂O₃) which is higher than the value of 8.0 w/o Y2O3 that according to Norton Co. should be present in NCX-34 Si3N4. Furthermore, the Y_2O_3 content varied considerably throughout the billet. It was noted, however, that if this material was subjected to a standard nitriding cycle to 1375°C for 60 hrs in N_2 , on subsequent oxidation for 190 hrs at 930°C no weight gain occurred and the strength of the material actually increased. However, at lower temperatures (730°C), disastrous oxidation still occurs but at a much slower rate. Due to the oxidation problems of NCX-34 Si₃N₄ that were encountered during this and other programs, the Norton Co. withdrew this material from the commercial market. The problem of NCX-34 Si₃N₄ further emphasizes the fact that the Si₃N₄-Y₂O₃-SiO₂ system is not fully understood and that continued investigation is necessary to identify the processing parameters and phase relationships in the system that control most of the thermal and mechanical properties.

The RT 4-pt bend strength and the RT and 1370° C ballistic impact strength of NCX-34 and NC-132 $\mathrm{Si_3N_4}$ control samples was determined. The RT 4-pt bend strength of 848 MPa (123 ksi) for the NCX-34 was 25% higher than the NC-132 $\mathrm{Si_3N_4}$. The RT ballistic impact resistance for the NCX-34 of 2.8 joules (2.1 ft-1bs) was almost 50% higher than the NC-132 $\mathrm{Si_3N_4}$, while the 1370 C ballistic impact resistance of both types of $\mathrm{Si_3N_4}$ was approximately the same.

In order to evaluate the effect of energy absorbing surface layers of RSSN on the strength of the hot-pressed $\mathrm{Si}_3\mathrm{N}_4$ substrate, a series of nitriding runs in pure N_2 under different nitriding conditions was done, using both -325 mesh and -100, +200 mesh Si powder layers on NC-132 $\mathrm{Si}_3\mathrm{N}_4$ substrates. These tests showed that nitriding conditions that resulted in substantial conversion of Si to

 $\mathrm{Si}_3\mathrm{N}_4$ (1370°C, 24 hrs) resulted in severe strength degradation (~325 MPa) of the NC-132 $\mathrm{Si}_3\mathrm{N}_4$ when the layered side was tested in tension, while nitriding conditions of 1250°C, 24 hrs that resulted in only slight conversion of Si to $\mathrm{Si}_3\mathrm{N}_4$ (~10%) did not lead to strength degradation of the $\mathrm{Si}_3\mathrm{N}_4$ substrate. Examination of fracture surfaces revealed that the fracture origin of degraded samples appeared to be small voids within the RSSN layer lying very close to the RSSN/HPSN interface.

RT 4-pt bend tests of NCX-34 $\mathrm{Si}_3\mathrm{N}_4$, nitrided to $1375^{\circ}\mathrm{C}$ for 60 hrs in N_2 , with well bonded RSSN surface layers indicated that, as previously found for NC-132 $\mathrm{Si}_3\mathrm{N}_4$, the nitriding of the Si powder layers introduces strength limiting flaws at the HPSN/RSSN interface that result in a 40-50% drop in bend strength when the nitrided layer is tested in tension. Nitriding tests with Si powder lightly sprinkled on the NCX-34 tensile surfaces showed that the fracture origin of degraded samples was always associated with a nitrided particle of Si or a depression that appeared to be at one time associated with a nitrided Si particle.

However, results of 4-pt bend tests on NC-132 and NCX-34 $\rm Si_3N_4$ with RSSN layers of various purity nitrided in a $\rm N_2/H_2$ mixture indicate that a minimal amount of substrate degradation occurs for well bonded layers of 98% purity -325 Si and -200 Si on both NCX-34 and NC-132 $\rm Si_3N_4$. Nitriding in $\rm N_2/H_2$ mixtures (96% $\rm N_2/4\%$ $\rm H_2$) also led to a much faster rate of conversion of the Si to $\rm Si_3N_4$ and an $\rm \alpha$ to $\rm \beta$ -Si $_3N_4$ ratio of ~2:1, whereas nitriding in 100% $\rm N_2$ gave an RSSN product of ~70% $\rm \beta$, 30% $\rm \alpha$. The much greater amount of $\rm \alpha$ -Si $_3N_4$, which forms primarily as fine whisker-like crystals interconnecting the $\rm \beta$ -Si $_3N_4$ grains, may be responsible for the lesser amount of substrate degradation observed for the samples nitrided in $\rm N_2/H_2$ mixtures, due to the $\rm \alpha$ -Si $_3N_4$ whisker mat not allowing the $\rm \beta$ -Si $_3N_4$ grains to bond directly to each other or to the HPSN substrate. Thus, no large stress-concentrating flaws are bonded directly to the HPSN surface and cracks initiating in the RSSN layer cannot propagate directly through $\rm \beta$ -Si $_3N_4$ grains and into the HPSN substrate.

Ballistic impact tests at RT and 1370°C on NCX-34 $\text{Si}_{3}\text{N}_{4}$ substrates with RSSN layers fabricated from both -325 and -100, +200 Si powder indicated that fully nitrided RSSN layers (i.e., no residual Si) result in only modest (50-100%) improvement in impact resistance. To obtain optimum impact resistance of over 11 joules (8 ft-lbs), as previously found for -100, +200 Si RSSN layers on NC-132 $\text{Si}_{3}\text{N}_{4}$, a certain amount of residual silicon within the RSSN particles appears to be necessary. However, enough $\text{Si}_{3}\text{N}_{4}$ must be formed to strongly bond the particles to one another. For -100, +200 Si RSSN layers the optimum amount of residual Si for excellent ballistic impact resistance was found to be in the range of 15-25 vol %.

In order to obtain an RSSN energy absorbing layer with a smoother surface finish, -325 and -200 mesh Si powder was used to form RSSN layers containing residual Si. From nitriding experiments conducted first in 100% $\rm N_2$ and later in 96% $\rm N_2/4\%~H_2$ on both NC-132 and NCX-34 $\rm Si_3N_4$ substrates, it was found that a residual Si content of >20 vol % was necessary for optimum ballistic impact resistance. The highest RT ballistic impact resistance ever recorded during the course of this program of 14.5 ft-lbs (19.7 joules) was obtained for -325 Si RSSN layers on NCX-34 $\rm Si_3N_4$ substrates that were nitrided in a 96% $\rm N_2/4\%~H_2$ mixture according to a schedule that resulted in ~20 vol % residual Si in the RSSN layer. The program goal of 7 ft-lbs (9.5 joules) at RT and 1370°C was met and exceeded for ballistic impact samples of -325 and -200 Si layers, nitrided in $\rm N_2/H_2$ to yield 20 vol % residual Si, on either NC-132 or NCX-34 $\rm Si_3N_4$ substrates. The residual Si is apparently absorbing a great deal of energy as it is crushed and fractured by the ballistic projectile.

Task II of this program consisted of evaluating the effect of thermal cycling on the integrity of the RSSN/HPSN combinations, in particular the effect of silica formation within the RSSN layer on its ability to absorb energy during ballistic impact. To minimize silica formation, an oxidation barrier of CVD $\mathrm{Si}_3\mathrm{N}_4$ on top of the RSSN layer was also to be evaluated. In addition, the hot gas erosion characteristics of the RSSN layers at 1200 and 1370 $^{\mathrm{O}}\mathrm{C}$ in a Mach 0.8 gas stream were evaluated, both with and without a thin CVD $\mathrm{Si}_3\mathrm{N}_4$ overlayer.

It was found that thermal cycling 75 times between $150-200^{\circ}\text{C}$ to either 1200 or 1370°C does not adversely affect the ballistic impact resistance of NC-132 or NCX-34 Si₃N₄ control samples, tested at RT and 1370°C . Ballistic samples of NC-132 or NCX-34 Si₃N₄ with -325 or -200 RSSN layers containing ~25 vol % residual Si, when cycled 75 times between 150 and 1200°C or 200 and 1370°C , actually register an increase in ballistic impact resistance when tested, especially at 1370°C . The increase at 1370°C is undoubtedly due to the large amount of SiO₂ formed within the RSSN layers during cycling that is deforming plastically during impact. Even though large amounts of cristobalite (SiO₂) were formed within the RSSN layer during thermal cycling, it did not affect the bonding between the RSSN layer and the HPSN substrate. Also, the cristobalite formed mainly at the expense of the α -Si₃N₄ within the RSSN layer and thus did not reduce the residual Si content below the critical 20 vol % level.

Attempts to form a protective CVD $\mathrm{Si}_3\mathrm{N}_4$ overlayer on RSSN layers containing ~25 vol % Si were unsuccessful due to the interference of the Si with the deposition process. CVD $\mathrm{Si}_3\mathrm{N}_4$ could only be deposited at temperatures of $1400^{\,\mathrm{O}}\mathrm{C}$ or greater and at these temperatures pinholes were formed in the layer over residual Si particles. Attempts to deposit CVD $\mathrm{Si}_3\mathrm{N}_4$ at lower temperatures, where the Si vapor pressure would not be as high, were unsuccessful.

However, CVD SiC, which can be deposited at temperatures of $1100-1150^{\circ}$ C, was successfully deposited on -200 RSSN layers. CVD SiC overlayers thicker than ~50 μ (2 mils) tended to crack severely on cooling from deposition due to thermal expansion mismatch, and on subsequent thermal cycling tended to spall, offering no protection from oxidation. CVD SiC overlayers of $12-25\mu$ (0.5-1.0 mils) in thickness were deposited crack-free and, on thermal cycling, did offer substantial oxidation protection and no decrease in ballistic impact properties. While some internal oxidation of the RSSN layer still occurred, it is felt that an optimized CVD SiC overlayer could be extremely oxidation resistant.

Mach 0.8, 5 hr, hot gas erosion testing at sample temperatures of 1200°C and 1370°C were run on NC-132 and NCX-34 Si₃N₄ controls and on samples with -200 and -325 RSSN layers (25 vol % Si), both with and without CVD Si3N4 overlayers. For the Si_3N_4 controls, no surface recession or weight change was observed at 1200°C, while at 1370°C a very slight surface recession (2.5u) and weight gain (+0.1 mg) was observed for NC-132 $\mathrm{Si}_{3}\mathrm{N}_{4}$ and a rather large surface recession (25μ) and weight loss (-3.5 mg) for NCX-34 Si₃N₄. For the -325 and -200 RSSN layers, no surface recession was detected at 1200°C but there was a substantial weight gain (~20 mg) due to the formation of silica on and within the RSSN layers. Samples with CVD Si₃N₄ overlayers also exhibited ~20 mg weight gains, indicating that the CVD layer was not protecting the RSSN from oxidation, although no oxidation product was detected on the CVD Si₃N₄ surface. At 1370°C, the -325 and -200 RSSN layers did exhibit a small surface recession ($\sim 8\mu$) and a substantial weight gain (~12 mg). The samples with CVD Si3N4 overlayers again gained substantial weight but did not exhibit any measurable surface recession, indicating that the CVD $\mathrm{Si}_{3}\mathrm{N}_{4}$ layer is very erosion resistant even though it is not completely continuous over the RSSN surface.

Hot gas erosion tests of samples of NCX-34 and NC-132 $\mathrm{Si}_3\mathrm{N}_4$ with -200 RSSN layers (25 vol % Si) and overlayers of CVD SiC of 36 μ (1.5 mil) thickness showed that these overlayers were very resistant to surface recession and relatively good in oxidation protection. Compared to the CVD $\mathrm{Si}_3\mathrm{N}_4$, samples with CVD SiC overlayers gained less than 25% of the weight. Again, it is felt that an optimized CVD SiC overlayer could offer excellent oxidation and erosion protection for RSSN energy absorbing surface layers on hot-pressed $\mathrm{Si}_3\mathrm{N}_4$ substrates.

IV. TECHNICAL PROGRESS SUMMARY

4.1 Fabrication and Characterization of Specimens

4.1.1 Fabrication and Characterization of Hot-Pressed Si₃N₄ Substrate Material

The silicon nitride samples used in this investigation consist of Norton Co. hot-pressed $\mathrm{Si}_3\mathrm{N}_4$, both NC-132 with MgO additive and NCX-34 with $\mathrm{Y}_2\mathrm{O}_3$ additive. Bend specimens of dimensions 4.44 x 0.508 x 0.254 cm (1.75 x 0.200 x 0.100 in.) and ballistic impact specimens of dimensions 3.81 x 2.54 x 0.64 cm (1.50 x 1.00 x 0.25 in.) of both types were machined from 15.3 x 15.3 x 2.54 cm (6 x 6 x 1 in.) billets. The wide (0.508 x 4.44 cm) face of the bend specimen and the narrow (0.64 x 3.81 cm) face of the ballistic impact specimen were perpendicular to the billet hot press direction.

Randomly selected specimens from each billet were characterized as to density, grain size, impurity content, and surface defects. The grain size and morphology was determined by replication techniques using the electron microscope. Impurity content was determined by spectrochemical analysis. Zyglo dye penetrant inspection was used to detect surface cracks or pits.

The impurity content of the NC-132 and NCX-34 Si₃N₄ materials, along with their densities, is given in Table I. The major impurities in NC-132 $\mathrm{Si}_3\mathrm{N}_4$ are Al, Fe, Mg, and W. The Mg is added deliberately as MgO for densification purposes while the W is present as WSi2, resulting from WC pickup during milling of the powder prior to hot pressing. The major impurities in NCX-34 Si₃N₄ are Fe, W, and Y. In this material, the Y is added deliberately as Y_2O_3 for densification purposes. It is interesting to note that 7.15 w/o Y corresponds to 9.1% Y203, more than the 8.0 w/o Y203 that, according to Norton Co., is supposed to be present in the NCX-34 material. Subsequent chemical analysis of billet $\#\mathrm{F338355}$, which was machined into 4-pt bend samples, indicated that the yttrium content varied throughout the billet with the Y203 content ranging from 7.6 to 9.4%. The grain size and morphology of the NCX-34 and NC-132 Si₃N₄ can be seen from Fig. 1 and Table II. While the Si3N4 grain size and morphology is similar for the two materials, their etching characteristics (hot HF) are quite different, which is indicative of different grain boundary phases. The NC-132 $\mathrm{Si}_{\mathfrak{I}}\mathrm{N}_{h}$ etched very readily due to the magnesium silicate glassy phase that is present at grain boundaries and triple points. The NCX-34 material was very difficult to etch with very little etching occurring except for rather large areas of what appears to be a second crystalline phase, probably "H" phase (Y10Si6024N2). "H" phase was detected by X-ray analysis as well, and appears to be present in the amount of approximately 9 vol %.

All of the NCX-34 $\rm Si_3N_4$ samples cut from the three billets ordered from the Norton Co. exhibited a macrostructure that was visible to the naked eye. This macrostructure consisted of a lighter colored skeletal structure interspersed with dark regions. On immersion in Zyglo dye penetrant with subsequent examination under U.V. light, the light areas pick up the penetrant while the dark areas do not (Fig. 2). Although the NCX-34 $\rm Si_3N_4$ samples appear to contain either porosity or very small cracks, 4-pt bend tests conducted at RT gave a strength of 848 MPa (123 ksi), which is 25% higher than that recorded for NC-132 $\rm Si_3N_4$. Thus, the defects in NCX-34 $\rm Si_3N_4$ that are visible from Zyglo dye penetrant inspection, do not appear to compromise the strength properties of the material, at least at RT.

Included in the characterization study of NCX-34 $\mathrm{Si}_3\mathrm{N}_4$ were oxidation studies in the 700-1000°C range, since some $\mathrm{Si}_3\mathrm{N}_4\mathrm{-Y}_2\mathrm{O}_3$ materials have been known to exhibit poor oxidation properties in this temperature range. Previous studies at UTRC and Norton Co. indicated that the NCX-34 $\mathrm{Si}_3\mathrm{N}_4$ material did not exhibit oxidation problems in this temperature range. However, tests on the recently delivered material, in particular the bend specimens cut from billet #F338355 which contained 7.15 w/o Y, showed that after oxidation at $930^{\circ}\mathrm{C}$ for 100 hrs in air, the samples gained over 1 mg/cm² and suffered a reduction in strength from 848 MPa (123 ksi) to 675 MPa (98 ksi). The lighter colored areas started to turn very white after a few hours while some, but not all, of the darker areas remained quite dark, as shown in Fig. 3. After 150 hrs at $930^{\circ}\mathrm{C}$ a few samples became degraded to the point of exhibiting essentially no strength. Aging the NCX-34 $\mathrm{Si}_3\mathrm{N}_4$ material at $730^{\circ}\mathrm{C}$ in air produced even more pronounced degradation, with samples literally falling apart after only 48 hrs, as shown in Fig. 4.

An interesting sidelight to the oxidation characteristics of the NCX-34 $\mathrm{Si}_{3}\mathrm{N}_{4}$ is that samples that had been put through a nitriding cycle to 1375°C in N₂ for 60 hrs, while exhibiting a loss in strength due to this cycle from 848 MPa (123 ksi) to 725 MPa (105 ksi), did not gain any measurable weight when subsequently oxidized for 190 hrs at 930°C and actually exhibited an increase in strength to 930 MPa (135 ksi). Gazza, et al (Ref. 11) noted similar behavior for $Si_3N_4 + 13$ w/o Y_2O_3 samples nitrided in N_2/H_2 mixtures and subsequently oxidized at 1000°C. The mechanism responsible for this "healing" effect for oxidation prone $Si_3N_\mu-Y_2O_3$ materials is unknown at this time; however, it does not prevent disastrous oxidation from occurring at lower temperatures. A series of nitriding runs were conducted using both pure N2 and 96% N2/4% H2 mixtures for periods up to 65 hrs at 1375°C with subsequent oxidation at 730°C. While the NCX-34 Si₃N₄ samples put through the nitriding cycles did not degrade as rapidly as "as-received" samples during the subsequent 730°C oxidation treatment, they eventually did degrade. It took approximately 48 hrs at 730°C for visual cracks to form in the nitrided samples compared to less than 10 hrs in the as-received NCX-34 Si₃N₄.

Although the low temperature oxidation problems of the NCX-34 $\rm Si_3N_4$ procured for this program were extremely serious, and led the Norton Co. to remove the material from the commercial market, this phenomonon could not be studied further under the scope of the present contract. However, it was decided to use the material along with NC-132 $\rm Si_3N_4$ as a substrate for the evaluation of energy absorbing surface layers of reaction sintered $\rm Si_3N_4$ (RSSN). The reason for this decision was that all testing under the program was to be done either at RT or $\rm 1370^{\circ}C$, and the material was found to exhibit excellent strength properties at these temperatures. However, the problem of NCX-34 $\rm Si_3N_4$ further emphasizes the fact that the $\rm Si_3N_4$ -Y203-SiO2 system is not fully understood and that continued investigation is necessary to identify the processing parameters and phase relationships in the system that control most of the thermal and mechanical properties.

4.1.2 Fabrication and Characterization of RSSN/HPSN Combinations

The RSSN energy absorbing surface layers were fabricated in situ on ballistic impact and 4-pt bend samples of hot-pressed $\mathrm{Si}_3\mathrm{N}_4$ by nitriding a layer of Si powder applied to the sample from a liquid slurry. The Si powders used were purchased from Cerac, Inc. and consisted of two -325 mesh powders of 98% and 99.6% purities, a -200 mesh powder of 98.5% purity, and a -100, +200 mesh powder of 98.5% purity. The chemical analysis of the four powders used is given in Table III. The major impurities in the 98% and 98.5% pure powders consist of Fe, Al, Mn, and Ca. The major impurities in the -325 (99.6%) powder are Al and Pb. The surface area of the finer powders was also determined by the BET method. The results of this analysis are given in Table IV and show that the surface area of the -325 (98%) powder is greater than the -200 (98.5%) as would be expected, and that the -325 (99.6%) is substantially greater than the lesser purity -325 mesh powder, which was not expected.

The procedure for fabricating the RSSN layers on the HPSN ballistic and 4-pt bend samples was as follows. The -325 or -200 Si powder was mixed with enough distilled water to form a thick slurry. The -100, +200 mesh powder would not form a slurry with water that, when dried, could be handled without damaging the Si layer, so it was mixed with toluene + 5 wt % polystyrene to form a slurry that had good green strength when dried. The Si powder slurries were then applied to the HPSN samples to form a layer ~1.5 mm thick when dry. The samples were then loaded into Mo boats with loose fitting covers, which were then put into a mullite tube furnace with controlled atmosphere for nitriding. After nitriding, the RSSN layers were surface ground to a uniform thickness of 1 mm. Figure 5 shows three steps in forming an RSSN layer of -200 mesh Si powder on an NC-132 Si_3N_4 ballistic impact sample, starting from the dried Si powder slurry, through the nitriding step, and then the surface grinding. With a more precise method of applying the powder slurry, such as injection molding, the final grinding step would not be necessary.

Density measurements taken on RSSN surface layers have shown that, using the slurry method of fabrication, a fully nitrided -100, +200 Si layer would contain approximately 45% porosity, a -200 Si layer would contain ~30-35% porosity, while the -325 Si layers would contain ~25-30% porosity. Occasionally, large bubbles in the Si slurry would persist in the RSSN layer, creating very large pores. Samples with this type of porosity near the impact point would be rejected from the testing program. Any samples that exhibited poor bonding or cracking between the RSSN layer and the HPSN substrate would also be rejected from further testing. This problem was only encountered with the -325 Si (99.6%) RSSN layers, and even then only infrequently. Representative samples from each nitriding run were subjected to X-ray diffraction analysis in order to determine the relative amounts of $\alpha\text{-Si}_3N_4$, $\beta\text{-Si}_3N_4$, and free Si in the RSSN layer.

4.2 Ballistic Impact Testing

The ballistic impact testing procedure consisted of firing 4.4 mm diameter hardened chrome-steel pellets, weighing 0.34 gms, from a modified Crossman air pistol or rifle (for higher velocities) at the center of the ballistic impact sample protruding from the holding arrangement. The plates of $\mathrm{Si}_3\mathrm{N}_4$ were held at one end in a vise arrangement so that a 2.54 x 2.54 cm (1.0 x 1.0 in.) square 0.64 cm (0.25 in.) thick was available for impact. The pistol and rifle were pressurized by helium, which could be adjusted so that velocities of 99 to 230 m/sec (325 to 755 ft/sec) could be obtained for the pistol and 152 to 343 m/sec (500 to 1125 ft/sec) could be obtained for the rifle. These velocities were measured at a distance of 30 cm (12 in.) from the end of the gun barrel and it was at this distance that the samples were always positioned. The kinetic energy of the steel pellets available for impact could thus be varied from a low of 1.6 joules (1.2 ft-lbs) to a high of 19.7 joules (14.5 ft-lbs).

Ballistic impact tests were performed at RT and 1370°C . The 1370°C tests were done by heating the reverse side of the ballistic impact sample with an oxyacetelene torch until the front side registered a temperature of ~1370 °C as read by an optical pyrometer. Control samples of hot-pressed Si_3N_4 (i.e., those without a RSSN layer) were tested by setting the helium pressure at a value that corresponded to 145 m/sec pellet velocity and then impacting the sample. If the sample did not fracture, the helium pressure was raised in 50 psi increments until failure occurred. Often, five or more impacts would be necessary to fail the sample. Samples with RSSN layers could be impacted only once, since the RSSN layer was usually damaged or destroyed after impact, so that a number of samples were required to establish the velocity necessary to fracture the Si_3N_4 substrate.

4.2.1 Ballistic Impact Testing of Si3N4 Controls

Ballistic impact tests were performed on NCX-34 Si $_3$ N $_4$ controls at RT and 1370°C. NC-132 Si $_3$ N $_4$ ballistic tests had been done under the previous contract (Ref. 10) and were not repeated, except for a few to verify the previous results. The results of these tests are given in Table V. The average RT impact energy necessary to fail the 25.4 x 38.2 x 6.35 mm (1 x 1 $\frac{1}{2}$ x 0.25 in.) sample of NCX-34 Si $_3$ N $_4$ was 2.8 joules (2.1 ft-1bs), compared to NC-132 Si $_3$ N $_4$ that failed at 1.9 joules (1.4 ft-1bs). The increase in RT ballistic impact resistance of the NCX-34 Si $_3$ N $_4$ over the NC-132 Si $_3$ N $_4$ is consistent with the observation that Si $_3$ N $_4$ densified with Y $_2$ O $_3$ additive exhibits a significantly higher RT fracture toughness (K $_1$ C $_2$ 7 NN/m $_3$ /2) than Si $_3$ N $_4$ densified with MgO (K $_1$ C $_2$ 4.5 MN/m $_3$ /2) (Ref. 12).

At $1370^{\circ}C$, the ballistic impact resistance of the NCX-34 Si $_3N_4$ is approximately the same as at RT, being 2.6 joules (1.9 ft-1bs). This compares favorably to the value of 2.8 joules for NC-132 Si $_3N_4$ at $1370^{\circ}C$, which for this material is due to energy absorption through plastic deformation of the magnesium silicate grain boundary phase.

The fracture mode for NCX-34 $\mathrm{Si}_3\mathrm{N}_4$ is predominantly tensile failure on the reverse side of the sample at RT and indeterminate at $1370^{\circ}\mathrm{C}$. At $1370^{\circ}\mathrm{C}$, the samples tend to split longitudinally into two pieces with a very smooth fracture surface, whereas at RT they normally shatter into 4 or more pieces with very rough fracture surfaces and very definite fracture origins. In contrast, the NC-132 $\mathrm{Si}_3\mathrm{N}_4$ samples fail in a predominantly Hertzian mode at RT and a mixed Hertzian/tensile mode at $1370^{\circ}\mathrm{C}$.

4.3 4-Pt Bend Testing of NCX-34 and NC-132 Si₃N₄ Controls

NCX-34 and NC-132 Si $_3$ N $_4$ bend specimens of dimensions 4.44 x 0.508 x 0.254 cm (1.75 x 0.200 x 0.100 in.) were tested in 4-pt bending at RT. All 4-pt bend testing was done using an inner span of 1.9 cm (0.75 in.) and an outer span of 3.81 cm (1.5 in.) at a crosshead speed of 0.25 cm/min (0.1 in/min). The average bend strength of NCX-34 Si $_3$ N $_4$ controls was 848 MPa (123 ksi), which was substantially higher than that found for NC-132 Si $_3$ N $_4$ of 662 MPa (96 ksi). The fracture origin invariably was located at a surface flaw (mostly at corners) introduced by the machining process. All samples had been longitudinally ground with a 400 grit diamond grinding wheel.

4.4 Task I - Development of RSSN Energy Absorbing Turface Layers on Hot-Pressed Si₃N₄

Previous work (Ref. 10) had indicated that relatively thin layers (~1 mm) of reaction sintered $\mathrm{Si}_3\mathrm{N}_4$ (RSSN), formed in situ on hot-pressed $\mathrm{Si}_3\mathrm{N}_4$ substrates by nitriding a layer of Si powder, increased the ballistic impact resistance of the substrate by up to a factor of seven. The most successful RSSN layer was fabricated from -100, +200 mesh Si powder. RSSN layers fabricated from -200 and -325 mesh powder were less successful in increasing impact resistance. It was surmised from this that for maximum impact resistance, a large grain size, large pore size RSSN layer was necessary.

4.4.1 Ballistic Impact Testing of RSSN/HPSN Combinations

In order to verify the previous results, which had been obtained using NC-132 $\mathrm{Si}_3\mathrm{N}_4$ substrates, a nitriding run was done using NCX-34 ballistic impact samples with both -325 Si and -100, +200 Si layers. All samples were nitrided in one run using the standard schedule of 20 hrs at $1150^{\circ}\mathrm{C}$ in Ar, 24 hrs at $1250^{\circ}\mathrm{C}$ in N_2 , followed by 60 hrs at $1375^{\circ}\mathrm{C}$ in N_2 . Ballistic impact tests were performed on these samples at RT and $1370^{\circ}\mathrm{C}$, the results of which are given in Table VI.

The state of the s

From these tests, it was found that the NCX-34 Si₃N₄ with -325 Si nitrided surface layers could withstand only 6.2 joules at RT and 4.9 joules at 1370°C before fracturing. The samples with -100,+200 Si nitrided surface layers withstood even less; 4.9 joules at RT and 3.7 joules at 1370°C. While these values represent an improvement of 50-125% in ballistic impact resistance over samples without RSSN layers, they were still much less than found previously for RSSN layers on NC-132 Si₃N₄. The reason for this appears to be due to the fact that the RSSN layers in these tests were essentially completely nitrided, even the -100, +200 Si layers. From X-ray results on the nitrided -100, +200 Si layers, less than 5 vol % unreacted Si was detected. Photomicrographs of these layers confirm this finding, as shown in Fig. 6. This figure shows the interface between the nitrided -100, +200 Si layer (top) and the NCX-34 Si₃N₄ substrate (bottom). Only the large $\beta-Si_3N_4$ particles with very small amounts of unreacted Si are evident in the RSSN layer, due to the fact that the resin used to infiltrate the sample for polishing purposes (dark grey phase) has destroyed most of the fine $\alpha-Si_3N_4$ needles that exist between the large $\beta-Si_3N_4$ particles. X-ray analysis indicates that this RSSN layer consists of ~70% β, 30% α-Si₃N₄.

Previously tested -100, +200 Si layers on NC-132 $\mathrm{Si}_3\mathrm{N}_4$ contained a substantial amount (~15-20 vol %) of unreacted silicon in the interior of the nitrided particles. The reason for the complete nitridation of the -100, +200 Si powder particles on NCX-34 $\mathrm{Si}_3\mathrm{N}_4$ is not clear, since the standard nitriding schedule of 20 hrs in Ar at $1150^{\circ}\mathrm{C}$, 24 hrs in N_2 at $1250^{\circ}\mathrm{C}$, and 60 hrs in N_2 at $1375^{\circ}\mathrm{C}$, has been used almost exclusively throughout the program.

In order to evaluate the effect of unreacted Si on the ballistic impact resistance, both NC-132 and NCX-34 $\mathrm{Si}_3\mathrm{N}_4$ substrates with layers of -100,+200 Si were nitrided according to the above schedule except that the $1375^{\circ}\mathrm{C}$ nitridation step was reduced to 24 hrs. From X-ray analysis and optical microscopy of the nitrided layers, it was found that this nitriding schedule resulted in approximately 25-30 vol % unreacted Si in the interior of the -100, +200 nitrided Si particles, as shown in Fig. 7. The results of RT ballistic impact tests on these samples are given in Table VII.

From Table VII, it can be seen that an impact energy in excess of 9.1 joules is necessary to fracture the NC-132 substrates with over 11.4 joules being necessary to fracture the NCX-34 $\mathrm{Si}_3\mathrm{N}_4$ substrates. These results are more in line with previous results for NC-132 $\mathrm{Si}_3\mathrm{N}_4$ and are what was anticipated for NCX-34 $\mathrm{Si}_3\mathrm{N}_4$, based on its higher ballistic impact resistance at RT over NC-132 $\mathrm{Si}_3\mathrm{N}_4$. It thus appears that to obtain maximum ballistic impact resistance from a RSSN layer on dense $\mathrm{Si}_3\mathrm{N}_4$, a certain amount of unreacted Si is necessary.

Further nitriding tests were done on ballistic samples of NCX-34 $\mathrm{Si}_3\mathrm{N}_4$ with both -325 Si and -100,+200 Si layers using the normal schedule except with only an 8 hr hold at the maximum temperature of 1375°C. A few of the -100,+200 Si samples were placed in the nitriding furnace in such a position that the maximum temperature was only ~1300°C.

The results of RT ballistic impact rests on the samples nitrided to $1375^{\circ}C$ for 8 hrs are given in Table VIII. As in the case of -100, +200 Si layers nitrided for 24 hrs at $1375^{\circ}C$, an impact energy in excess of 11.4 joules was necessary to fracture the NCX-34 Si₃N₄ substrates. However, the nitrided -325 Si layers could only withstand up to 6.2 joules before the substrate fractured. From X-ray analysis and optical microscopy of the nitrided layers, it was found that the 8 hr, $1375^{\circ}C$ nitriding schedule resulted in approximately 60% unreacted silicon within the large β -Si₃N₄ grains of the -100,+200 Si nitrided layer (Fig. 8), while the -325 Si nitrided layers were essentially completely nitrided (Fig. 9) to a mixture of ~65% β , 35% α -Si₃N₄.

The -100,+200 Si samples that were deliberately nitrided to only 1300° C, 8 hrs, exhibited RT ballistic impact resistance less than the -100,+200 Si samples nitrided to 1375° C, 8 hrs. They were also somewhat friable, indicative of poor particle-to-particle bonding. From X-ray analysis and optical microscopy it was evident that very little of the Si had been converted to Si_3N_4 (~10 vol %), as shown in Fig. 10. Not enough Si_3N_4 had been formed to bond the particles together, thus resulting in the observed friable layer.

It thus appears obvious that some residual silicon must be present in the RSSN layer in order to achieve maximum ballistic impact resistance. However, enough Si₃N₄ must be formed to strongly bond the particles to one another. Since the samples with -100,+200 Si layers containing ~60 vol % residual silicon did not exhibit any greater impact resistance than those with ~25 vol % residual silicon, it would appear that to avoid any possible thermal expansion mismatch problems, only the minimum amount of residual silicon necessary to achieve maximum impact resistance should remain in the RSSN layer. For -100,+200 Si layers this optimum amount of residual silicon appears to be in the range of 15-25 vol %.

4.4.1.1 RT Ballistic Impact Testing of Fine Grained RSSN Layers

Since it appeared that the excellent impact properties of -100, +200 RSSN layers were related to the amount of residual Si present, it was decided to determine if finer grained RSSN layers fabricated from -325 or -200 Si and containing residual Si after nitriding could achieve the same results. To date, almost all of the -325 or -200 Si layers studied have been fully nitrided. The finer grained RSSN layers could offer certain advantages over the -100, +200 Si RSSN layers due to their smoother surfaces and ease of fabrication. Accordingly, nitriding experiments with -325 Si and -200 Si layers on ballistic samples of both NC-132 and NCX-34 Si $_3$ N $_4$ in N $_2$ and N $_2$ /N $_2$ mixtures for varying lengths of time at the maximum nitriding temperature of 1375 C were run.

The first nitriding experiments were run in pure N_2 for a period of 1 hr at the maximum nitriding temperature of 1375°C . The -200 Si layers nitrided under these conditions appeared to contain approximately 30 vol % unreacted Si, as determined from X-ray analysis and optical microscopy. The determination of the relative amounts of $\alpha\text{-Si}_3N_4$, $\beta\text{-Si}_3N_4$, and free Si was done using the method of Gazzara, et al (Ref. 13). The -325 layers nitrided under the same conditions contained approximately 20 vol % unreacted Si. The Si $_3N_4$ in both samples was a mixture of ~55% β , 45% α .

The results of RT ballistic impact tests of NC-132 and NCX-34 $\rm Si_3N_4$ with the above layers are presented in Table IX. Most of the samples in this nitriding run were NC-132 $\rm Si_3N_4$ and, from Table IX, it can be seen that both -325 Si and -200 Si RSSN layers on NC-132 $\rm Si_3N_4$ required an impacting energy of 15.4 joules in order to fracture the substrate. Figure 11 shows the NC-132 $\rm Si_3N_4$ sample with a -200 Si RSSN layer that was impacted at 230 mps (9.1 joules). Note that the RSSN layer was destroyed only at the point of impact. This value is higher by almost 2 joules than the previously obtained value of 13.6 joules for -100. +200 Si RSSN layers on NC-132 $\rm Si_3N_4$ that contained ~20 vol % unreacted Si.

Only two samples of NCX-34 $\mathrm{Si}_3\mathrm{N}_4$ were included in the 1 hr, $1375^{\circ}\mathrm{C}$, N_2 nitriding run; one with a -325 Si layer and one with a -200 Si layer. Both of these samples withstood an impacting energy of 15.4 joules without failure of the substrate. This demonstrates once again that, at least at RT, NCX-34 $\mathrm{Si}_3\mathrm{N}_4$ has greater ballistic impact tolerance than NC-132 $\mathrm{Si}_3\mathrm{N}_4$, both with and without RSSN energy absorbing surface layers.

Since it was found on this program that nitriding in a 96% $\rm N_2/4\%~H_2$ atmosphere instead of pure $\rm N_2$ resulted in minimal strength degradation of both NC-132 and NCX-34 $\rm Si_3N_4$ when RSSN layers of -325 $\rm Si$ (98%) were tested in 4-pt bending with the layered side in tension, as discussed in a following section, it was decided to continue further short time nitriding tests using the $\rm N_2/H_2$ mixture as the nitriding media. Accordingly, a repeat of the previous nitriding run of Ar, $\rm 1150^{\circ}C$, 20 hrs followed by $\rm 1250^{\circ}C$, 24 hrs, in $\rm N_2$, and then 1 hr at $\rm 1375^{\circ}C$ in $\rm N_2$, was done using 96% $\rm N_2/4\%~H_2$ in place of the 100% $\rm N_2$. Both NC-132 and NCX-34 $\rm Si_3N_4$ substrates were used with -200 $\rm Si$ layers but only NCX-34 $\rm Si_3N_4$ was used with -325 $\rm Si$ layers.

From X-ray analysis and optical microscopy it was found that the -200 Si layers contained ~21 vol % residual Si (Fig. 12) down from ~30 vol % for -200 Si layers nitrided in N_2 for 1 hr at 1375°C, while the -325 Si layers contained only ~5 vol % residual Si (Fig. 13) down from ~20 vol % for -325 Si layers nitrided in N_2 . It was also found that the microstructure of the layers nitrided in N_2/H_2 mixtures was quite different than the same layers nitrided in 100% N_2 . There was much more evidence of fine grained $\alpha-\mathrm{Si}_3N_4$ around the larger $\beta-\mathrm{Si}_3N_4$ grains. This has also been observed recently by Lindley, et al (Ref. 14). This was substantiated by the X-ray analysis of both the -325 Si and -200 Si layers indicating that the Si_3N_4 present consisted of more α than β ; 73% α , 27% β for the -200 Si layers and ~58% α , 42% β for the -325 Si layers. This is in contrast to the same layers nitrided under identical conditions except using 100% N_2 , where the $\beta-\mathrm{Si}_3N_4$ content was always greater than the $\alpha-\mathrm{Si}_3N_4$.

The results of RT ballistic impact tests on these samples are given in Table X. As in the case of -200 Si layers nitrided for 1 hr at 1375 $^{\rm O}$ C in N $_2$, these layers nitrided in N $_2$ /H $_2$ under the same conditions resulted in impact energies of 15.4 joules being necessary to fracture the NC-132 Si $_3$ N $_4$ substrates while 17.2 joules was necessary to fracture the NCX-34 substrates. Figures 14 and 15 show the NCX-34 Si $_3$ N $_4$ /-200 RSSN ballistic samples after 15.4 and 17.2 joule impacts, respectively. However, the -325 Si layers on NCX-34 Si $_3$ N $_4$, nitrided in N $_2$ /H $_2$ for 1 hr at 1375 $^{\rm O}$ C, and containing only 5 vol % unreacted Si, required a rather low impact energy of 9.1 joules to fracture the substrate. It is thus obvious that more than 5 vol % is necessary in the RSSN layers for maximum impact resistance.

In order to determine the minimum amount of residual Si necessary in RSSN layers on dense $\mathrm{Si}_3\mathrm{N}_4$ for maximum impact resistance, further nitriding tests were carried out using -325 and -200 Si powder layers on NCX-34 $\mathrm{Si}_3\mathrm{N}_4$ substrates. Samples were nitrided in $\mathrm{N}_2/\mathrm{H}_2$ at a maximum temperature of 1375°C for periods of 30 min, l^1_2 hrs, and 2 hrs for the -200 Si layers and for 30 min for the -325 Si layers. Quantitative X-ray analysis showed that for samples nitrided for 30 min at 1375°C, the -325 Si layers consisted of 20 vol % Si, 55 vol % α -Si $_3\mathrm{N}_4$, and 25 vol % β -Si $_3\mathrm{N}_4$, while the -200 Si layers contained 25 vol % Si, 50 vol % α -Si $_3\mathrm{N}_4$, and 25 vol % β -Si $_3\mathrm{N}_4$. The amount of residual Si in -200 layers nitrided for l^1_2 hrs was ~14% while those nitrided for 2 hrs was ~6%.

The RT ballistic impact results for these and the previously tested samples nitrided for 1 hr at 1375°C are given in a shortened form in Table XI. Only the test results for samples that fall on either side of the energy required to fracture the Si_3N_4 substrate are shown. From Table XI, it is evident that nitriding -200 Si layers in N_2/H_2 for much more than 1 hr at 1375°C results in too much conversion of Si to Si_3N_4 with accompanying reduction in ballistic impact resistance. Residual Si content of greater than ~20 vol % does not lead to increases in ballistic impact resistance at RT. For maximum impact resistance with minimum residual Si content for -200 Si RSSN layers, a nitriding schedule of ~1 hr at a maximum temperature of 1375°C in a 96% $\text{N}_2/4\%$ H₂ mixture appears to be optimal.

For the finer grain size -325 Si RSSN layers, a shorter nitriding time at 1375°C is necessary for optimum ballistic impact resistance, compared to the -200 Si layers. In fact, -325 Si layers on NCX-34 Si $_3\text{N}_4$ substrates nitrided for 30 min at 1375°C in N_2/H_2 , when tested at RT in ballistic impact, could not be fractured within the limits of the ballistic impact equipment. The maximum velocity obtainable is 343 m/sec (1125 ft/sec) which is equivalent to an impacting energy of 19.7 joules (14.5 ft-1bs). This energy was insufficient to fracture the above mentioned samples, which represents the highest as-nitrided RT ballistic impact resistance ever recorded under this program.

One additional type of RSSN layer containing ~20 vol % Si was tested in ballistic impact at RT. These layers consist of 75 vol % -325 Si and 25 vol % -100, +200 Si. The nitriding schedule was such that essentially all of the -325 Si was converted to $\mathrm{Si}_3\mathrm{N}_4$ while only a small amount of -100, +200 Si particles were reacted. Thus, the layer consisted of a fine grained fully nitrided matrix with large Si particles interspersed throughout. Ballistic impact testing of this type of RSSN layer on NCX-34 $\mathrm{Si}_3\mathrm{N}_4$ substrates gave a maximum impact energy without substrate failure of 13.6 joules. This value, while substantial, was lower than the values obtained for -200 and -325 RSSN layers and was more comparable to previously obtained results using 100% -100, +200 Si layers. The smoothness of the layer was also not as good as that obtained for either -200 or -325 RSSN layers. Thus, the mixed particle size layers were dropped from further consideration.

4.4.1.2 1370°C Ballistic Impact Testing of Fine Grained RSSN Layers

Ballistic impact tests at 1370°C were also performed on NC-132 and NCX-34 Si₃N₄ substrates with RSSN layers fabricated from both -325 and -200 Si powder. Two types of RSSN layers were investigated, one with 5 vol % residual Si and one with ~25 vol % Si. The results of these tests are given in Tables XII and XIII.

Table XII shows the RT and 1370°C ballistic impact resistance for -325 Si RSSN layers with 5 vol % residual Si on both NC-132 and NCX-34 Si $_3$ N $_4$ substrates. The impact resistance of RSSN layers with 5 vol % Si on NC-132 Si₃N₄ substrates is substantially higher at 1370°C than at RT, reflecting the greater impact resistance of NC-132 Si₃N₄ at elevated temperature. The impact resistance of RSSN layers containing 5 vol % Si on NCX-34 Si $_3N_4$ at RT is somewhat higher than the same layers on NC-132 Si₃N₄, as expected. However, at 1370°C the impact resistance for the NCX-34 Si₃N₄/RSSN samples drops considerably, and is much inferior to NC-132 Si₃N₄/RSSN material. The fracture of the samples with NCX-34 substrates at $1370\,^{\circ}$ C is rather unusual. On impact, the samples split in half in the direction normal to the hot-pressing direction. The origin of fracture is rather difficult to discern since the fracture surface is extremely flat. However, when the samples were photographed using oblique lighting, the fracture origin became discernible. Figure 16 shows a sample of NCX-34 Si3N4 with an RSSN layer fabricated from -325 Si with 5 vol % residual Si, that was impacted at 1370°C at a velocity of 169 m/sec (4.9 joules). The RSSN layer has, for the most part, remained strongly bonded to the substrate while the NCX-34 Si₃N₄ substrate has failed in the usual manner for this material at 1370°C. Figure 17 shows one side of the fracture surface of this sample. It appears that the fracture origin is located near a corner (i.e., the top edge) of the substrate, approximately 8 mm away from the point of impact. This type of fracture was typical for most of the NCX-34 3i₂N₁, samples impacted at 1370°C.

Table XIII gives the results of 1370°C ballistic impact tests for -325 and -200 Si RSSN layers on both NC-132 and NCX-34 Si₃N₄ substrates with ~25 vol % residual Si present in the RSSN layers. Similar to the results obtained at RT, RSSN layers of both -325 and -200 Si, on either NC-132 or NCX-34 Si₃N₄, that contain >20 vol % residual Si, result in much greater ballistic impact resistance than RSSN layers with less than 20 vol % Si. Again, as found for RSSN layers with 5 vol % Si, the samples with NC-132 substrates exhibited greater impact resistance at 1370°C than similar samples with NCX-34 Si₃N₄ substrates. The fracture origin for the NCX-34 samples was again difficult to determine. The -325 RSSN layers on NC-132 substrates gave slightly higher impact values than the -200 RSSN layers, as was noted at RT for these layers (with 20 vol % Si) on NCX-34 substrates.

A summary of all ballistic impact tests of RSSN layers on NC-132 and NCX-34 $\mathrm{Si}_3\mathrm{N}_4$ substrates is presented in bar graph form in Figs. 18 and 19, respectively. From these figures, it is immediately obvious that maximum impact resistance for any given particle size RSSN layer is only obtained when that layer contains >20 vol % unreacted Si.

4.4.1.3 Ballistic Impact Observations

The role of the residual Si within RSSN energy absorbing surface layers in maximizing the tolerance of the RSSN/HPSN combinations to ballistic impact of hardened chrome-steel spheres is not fully understood. It appears that the residual Si absorbs the spheres' energy and slows it as the Si is crushed, fractured, and, it appears, actually ignited by the friction caused by the impact event. Figures 20a and 20b show the impact surface of a steel ball after RT impact with a control sample of NCX-34 Si $_3$ N $_4$ at a velocity of 130 m/sec (2.8 joules). This velocity is sufficient to fracture the NCX-34 Si $_3$ N $_4$ sample. The steel sphere in Fig. 20 is considerably flattened and exhibits cracks that originated at the point of impact. In Fig. 20b the grinding marks from the Si $_3$ N $_4$ surface can be seen imprinted on the contact area of the steel sphere.

Figures 21a and 21b show the impact surface of a steel ball after RT impact with an NCX-34 $\rm Si_3N_4$ sample having a -200 RSSN surface layer with ~6 vol % residual Si. The impacting velocity was 230 m/sec (9.1 joules) which was sufficient to fracture the NCX-34 $\rm Si_3N_4$ substrate. The surface of the sphere is roughened by passing through the RSSN layer and the contact area with the NCX-34 $\rm Si_3N_4$ substrate is quite small. Some particles of RSSN layer appear to be adhering to the surface of the sphere.

Figures 22a and 22b show the impact surface of a steel sphere after RT impact with an NCX-34 Si_3N_4 sample having a -200 RSSN surface layer containing 21 vol % residual Si. The surface of the sphere is very abraded and roughened with no contact area with the substrate visible. Large particles of the RSSN layer appear to be imbedded in the surface and, although not apparent in this view, the impacting surface of the sphere has been slightly worn away by passing through the RSSN layer, losing ~.5 mg of weight. Figure 23 shows the impact point at the bottom of a hole created in a -200 RSSN layer by a steel sphere impacting at a velocity of 300 m/sec. Flattening of the RSSN layer near the impact point is quite evident. At the moment of impact of a steel sphere with an RSSN layer containing considerable residual Si, a flash of sparks can be seen emanating from the impact point. These sparks are apparently ignited Si particles caused by frictional heating during the impact event. The striations seen on the RSSN surface in Fig. 23 are evidently caused by the outward passage of these particles. Whatever the actual mechanism, the Si particles in the RSSN layer definitely tend to slow down the incoming steel sphere to a greater extent than RSSN layers with little or no residual Si.

Another important observation concerning the RSSN energy absorbing surface layer concept is that, while most of the RSSN/HPSN combinations tested in ballistic impact had RSSN layers of 1 mm thickness, a substantial amount of energy can be absorbed by much thinner layers, as shown in Table XIV. Even a 0.25 mm thick RSSN layer absorbs 4 times the amount of energy of an NC-132 $\rm Si_3N_4$ substrate with no layer. This is important due to the fact that some components could be too small to accommodate a standard RSSN layer of 1 mm thickness.

4.4.2 4-Pt Bend Testing of RSSN/HPSN Combinations

From previous work on energy absorbing RSSN surface layers on NC-132 Si $_3N_4$ (Ref. 10), it had been shown that a severe strength degradation occurred when the RSSN/HPSN sample was tested in either Charpy impact of bending with the RSSN side in tension. In order to determine at what point in the nitriding cycle the strength degradation at the RSSN/HPSN interface occurs, a series of nitriding runs were done under differing conditions, using both -325 Si and -100, +200 Si powder layers on NC-132 and NCX-34 substrates. Sets of Si $_3N_4$ bend samples (4.44 x 0.508 x 0.254 cm) with the two different Si powder layers were subjected to four different cycles: (1) Ar, 1150°C, 20 hrs; (2) Ar, 1150°C, 20 hrs, plus N $_2$, 1250°C, 24 hrs; (3) Ar, 1150°C, 20 hrs, plus N $_2$, 1250°C, 24 hrs; and (4) the normal nitriding cycle of 20 hrs in Ar at 1150°C, 24 hrs in N $_2$ at 1250°C, followed by 60 hrs in N $_2$ at 1375°C. The samples were then tested in 4-pt bending at RT with the RSSN (or Si) layer in tension.

The results of these tests are given in Table XV. It is apparent that degradation of the sample strength does not occur until the nitriding temperature of 1375°C is reached. A nitriding time of 24 hrs at this temperature is sufficient to degrade the strength of nitrided NC-132 and NCX-34 Si₃N₄ samples with -325 mesh Si layers to half the control value, with longer times being necessary to achieve this with the coarser -100, +200 mesh Si layers. Note that NC-132 Si₃N₄ by itself appears to increase somewhat in strength after undergoing the standard nitriding cycle, while the NCX-34 Si₃N₄ is decreased in strength somewhat. The intermediate temperature strength degradation problem of this lot of NCX-34 Si₃N₄ may be contributing to the loss in strength, even though the nitriding treatment is carried out in a nonoxidizing environment.

An X-ray diffraction analysis of the nitrided -325 Si layers after 24 hrs at 1250°C in N_2 indicates that the layer consists primarily of Si, with only about 10 vol % of the Si converted to Si_3N_4 . In contrast, the samples nitrided to 1375°C for 24 hrs exhibited over 90 vol % conversion to a mixture of α and β Si_3N_4 . It thus appears that as soon as a substantial amount of the Si powder layer reacts with the N_2 to form Si_3N_4 , either the surface of the Si_3N_4 substrate becomes a source of stress concentrating flaws due to interaction with the nitrided Si grains, or that the interfacial bonding is increased to the point that cracks propagating through the RSSN layer during stressing are not blunted or deflected at the RSSN/HPSN interface but continue to propagate into the HPSN.

The fracture surfaces of -325 Si layers on NC-132 Si $_3$ N $_4$ nitrided at maximum temperatures of 1250°C and 1375°C for 24 hrs were examined by scanning electron microscopy (SEM). The 1250°C nitrided sample is shown in Fig. 24. This particular sample had a 4-pt bend strength of 586 MPa (85 ksi) which is somewhat less than the control value of 662 MPa (96 ksi). The fracture surface is fairly rough with the fracture origin located near the sample edge. The origin is indicated by arrows in Fig. 24 and appears to be a small void within the NC-132 Si $_3$ N $_4$ at a distance of ~20 μ from the tensile surface. The nitrided Si surface layer does not appear to have influenced the fracture of this sample and actually has debonded from the NC-132 Si $_3$ N $_4$ near the fracture origin.

Figure 25 shows the fracture surface of the -325 Si sample nitrided at $1375\,^{\circ}\text{C}$ for 24 hrs. The nitrided Si layer is primarily converted to Si_3N_4 and is quite strongly bonded to the NC-132 Si $_3\text{N}_4$. The fracture surface of the NC-132 Si $_3\text{N}_4$ is very smooth, which is indicative of a sample with low bend strength; in this case 300 MPa (44 ksi). The fracture origin is indicated by arrows in Fig. 25 and appears to be a void of about 20 μ diameter in the RSSN layer located about 50μ from the NC-132 Si $_3\text{N}_4$ interface. This particular sample appears to have had a few very large bubbles (i.e. voids) in the RSSN layer but they do not appear to affect the nature of fracture. Other -325 Si layers, nitrided at $1375\,^{\circ}\text{C}$, containing no large voids exhibit the same type of fracture behavior.

Some RSSN/HPSN combinations were rather difficult to fabricate with a well bonded interface, in particular the -325 RSSN layers on NCX-34 $\mathrm{Si_3N_4}$ substrates. A typical fracture surface for a weakly bonded -325 RSSN layer on NCX-34 $\mathrm{Si_3N_4}$ is shown in Fig. 26. The RSSN layer on this sample is still adhered to the substrate; many -325 RSSN layers debonded when the samples were broken. The relatively rough surface of the NCX-34 substrate cross section is indicative of a strong sample, in this case 702 MPa (102 ksi). Figure 27, by way of contrast, shows the quite smooth fracture surface of the substrate for a -100, +200 RSSN layer on NCX-34 $\mathrm{Si_3N_4}$ with a degraded strength of only 407 MPa (59.1 ksi). In this case, the fracture origin appears to be located at some point within the RSSN layer, near the interface.

In order to determine whether or not the strength degradation is due to interaction between the Si particles and the $\mathrm{Si}_3\mathrm{N}_4$ substrate during nitriding, NCX-34 $\mathrm{Si}_3\mathrm{N}_4$ samples that had both -325 Si and -100, +200 Si powder lightly sprinkled on the tensile surface were nitrided by the usual method. These samples, when tested at RT with the lightly covered RSSN surface in tension, exhibited significant degradation in strength. The fracture origin was always located on the surface at either a nitrided particle of Si or a depression that at one time was associated with a nitrided Si particle. Figure 28 shows a typical fracture origin for a sample with a surface covered with nitrided -100, +200 Si particles.

4.4.2.1 Bend Test of RSSN/HPSN Combinations Nitrided in a $\rm N_2/H_2$ Mixture

In order to insure that impurities in the Si powder or oxygen contamination from the nitriding gas are not contributing to the observed degradation, additional nitriding runs were done using a much purer Si starting powder and using a 96% $\rm N_2$ -4% $\rm H_2$ mixture as the nitriding media. Both NC-132 and NCX-34 $\rm Si_3N_4$ bend specimens were fabricated with approximately one mm thick layers of -190, +200 Si and -325 Si powder of two purities; a nominal 98% pure powder than has been used throughout this program and a high purity 99.6% powder. The chemical analyses of these powders was given previously in Table III. It can be seen that the main impurities in the -325 (99.6%) powder are Al and Pb (.1%) while the -325 (98%) powder contains Fe (.7%), Al (.2%), Mn (.3%), Cr (.1%), and Ca (.1%). The samples were nitrided according to the standard schedule except that the nitriding atmosphere consisted of 96% $\rm N_2/4\%~H_2$, instead of the usual 100% $\rm N_2$.

The results of RT 4-pt bend strength tests with the RSSN in tension are given in Table XVI. It can be seen that both NCX-34 and NC-132 Si₃N_b with well bonded RSSN layers of 98% purity -325 Si are not significantly degraded in strength when the nitriding is carried out in a N_2/H_2 mixture. The 99.6% -325 Si and the -100, +200 Si of 98.5% purity, when nitrided using N2/H2 mixtures on both NC-132 and NCX-34 $\mathrm{Si}_{3}\mathrm{N}_{4}$ substrates, do tend to degrade the strength; although less so for the NCX-34 Si_3N_4 . For some reason, the -325 Si (99.6%) layers on NCX-34 Si₃N_h usually exhibit rather poor bonding. This may be due to the very small particle size, i.e. high surface area, of this powder causing debonding due to high shrinkage during drying of the Si layer. Figures 29 and 30 show the fracture surfaces of the -325 (98%) Si RSSN layers on NC-132 and NCX-34 Si₃N_b, respectively. The RSSN layers on both samples are very well bonded to the substrate and the fracture surfaces are quite rough, in agreement with the high strength of these samples. Shown in Fig. 31 is the usual fracture surface obtained when -325 Si (98%) layers on NC-132 Si₃N₄ are nitrided to 1375°C, 60 hrs, in pure N2. This sample exhibited a bend strength of 264 MPa (38.3 ksi) compared to 659 MPa (95.6 ksi) for the sample in Fig. 29 nitrided in 96% $N_2/4\%$ H2. The fracture origin for the samples nitrided in N2/H2 mixtures appears to be at or very near the RSSN/HPSN interface; near the right corner for the sample in Fig. 29 and midway between the left corner and center for the sample in Fig. 30. The fracture origin for the degraded sample in Fig. 31 is not readily apparent, but appears to be within the RSSN layer.

Subsequent 4-pt bend tests have been done on samples of both NC-132 and NCX-34 $\mathrm{Si}_3\mathrm{N}_4$ with -325 and -200 Si layers, that were nitrided in $\mathrm{N}_2/\mathrm{H}_2$ mixtures along with ballistic impact samples. Three bend test samples of each RSSN/HPSN combination were included in each nitriding run. All of the samples nitrided in the 96% $\mathrm{N}_2/4\%$ H₂ mixture showed some degradation in bend strength. The NCX-34 $\mathrm{Si}_3\mathrm{N}_4$ samples with either -325 or -200 RSSN layers containing 20+25 vol % Si

gave bend strengths that averaged 572 MPa (83 ksi). The NC-132 $\rm Si_3N_4$ samples with similar RSSN layers averaged 503 MPa (73 ksi). These results are also given in Table XVI. This represents a 32% drop in strength for the NCX-34 $\rm Si_3N_4$ and a 24% drop in strength for the NC-132 $\rm Si_3N_4$ over the as-received condition. However, the NCX-34 $\rm Si_3N_4$ degrades ~15% in strength due to the nitriding treatment alone. This drop in strength may be connected to the observed intermediate temperature oxidation problem of this NCX-34 $\rm Si_3N_4$ material. Figures 32 and 33 show all of the 4-pt bend strength data for NC-132 and NCX-34 substrates, respectively, with the various RSSN layers, plotted in bar graph form.

4.4.2.2 Conclusions on the Degradation of RSSN/HPSN Bend Strength

In general, when well-bonded RSSN layers on HPSN substrates are tested at RT in bending with the RSSN layer in tension, severe strength degradation (~50%) occurs for those samples nitrided in 100% $\rm N_2$ while only moderate to very little strength degradation occurs for those samples nitrided in 96% $\rm N_2/4\%~H_2$. Also, the strength retention is usually best for NCX-34 $\rm Si_3N_4$ over NC-132 $\rm Si_3N_4$, reflecting the higher initial strength of the NCX-34 material.

The reason for the strength degradation for those samples nitrided in 100% N_2 appears to be caused by the type of microstructure developed within the RSSN layer and the way it bonds to the HPSN substrate. RSSN nitrided in flowing N2 is comprised primarily of large particles of $\beta-Si_3N_4$, with very little $\alpha-Si_3N_4$ whisker formation between the β -Si $_3N_4$ particles, as discussed by Lindley, et al (Ref. 14). Bonding in this type of RSSN layer on a HPSN substrate consists primarily of direct β -Si₃N₄ to β -Si₃N₄ particle bonding and β -Si₃N₄ particle to HPSN substrate surface (also β -Si $_3N_4$) bonding. From experiments with sprinkled Si powder nitrided in 100% N $_2$ on HPSN substrates, it was found that the nitrided Si particles bond very strongly to the substrate with a continuous β -Si $_3N_4$ structure and act as large surface flaws, causing strength degradation. RSSN layers on HPSN substrates, nitrided in pure N2, cause strength degradation by allowing crack propagation to occur through the direct $\beta-Si_3N_4$ to $\beta-Si_3N_4$ particle bonding and then on through the HPSN substrate. The fact that most well-bonded RSSN/HPSN combinations, nitrided in pure N2, do not exhibit fracture origins at the RSSN/HPSN interface but rather somewhere in the RSSN layer indicates that flaws (i.e. porosity) in the RSSN structure are controlling the mode of fracture.

RSSN layers nitrided in N $_2$ /H $_2$ mixtures exhibit a much different microstructure than those nitrided in pure N $_2$. Every β -Si $_3$ N $_4$ particle, whether or not it contains residual Si in the center, is surrounded by a fine structure of α -Si $_3$ N $_4$ whiskers. This α -Si $_3$ N $_4$ whisker mesh separates the β -Si $_3$ N $_4$ grains from each other and from the HPSN substructure, thus not allowing a direct path for crack propagation. The flaw size within the RSSN nitrided in N $_2$ /H $_2$ mixtures is also considerably reduced, due to the pores between Si particles becoming filled with the fine α -Si $_3$ N $_4$ structure. Well bonded RSSN layers on HPSN substrates always exhibit fracture origins at the RSSN/HPSN interface, indicating

that the fracture mode is controlled by flaws at the interface, not within the RSSN layer as is the case when nitriding is done in pure N2. And, since the interface consists primarily of α -Si $_3$ N $_4$ whiskers bonded to the HPSN substrate, the flaws at the interface are not large, thus leading to minimal strength degradation.

4.4.3 Task I - Conclusions

The general goal of Task I of this program was to develop RSSN energy absorbing surface layers on hot-pressed $\mathrm{Si}_3\mathrm{N}_4$ that would consistently result in ballistic impact strengths at RT and $1370^{\circ}\mathrm{C}$ of over 7 ft-lbs (9.5 joules) while minimizing the RSSN/HPSN interfacial strength degradation that occurs as a result of the nitriding process. This goal has been accomplished with the development of RSSN layers of either -325 Si or -200 Si nitrided in a 96% $\mathrm{N}_2/4\%$ H₂ mixture, to minimize interfacial strength degradation, according to a schedule that results in at least 20 vol % residual Si remaining in the RSSN layer. Using either NC-132 or NCX-34 $\mathrm{Si}_3\mathrm{N}_4$ substrates in combination with these RSSN layers meets the 7 ft-lb (9.5 joule) goal at both RT and $1370^{\circ}\mathrm{C}$, with the NCX-34 $\mathrm{Si}_3\mathrm{N}_4$ material performing better at RT and the NC-132 $\mathrm{Si}_3\mathrm{N}_4$ material performing better at $1370^{\circ}\mathrm{C}$. The latter observation is undoubtedly due to the higher fracture toughness of $\mathrm{Si}_3\mathrm{N}_4$ (Y₂O₃) materials at RT and the greater plastic flow at the grain boundaries of $\mathrm{Si}_3\mathrm{N}_4$ (MgO) materials at elevated temperatures.

4.5 Task II - Effect of Thermal Exposures on RSSN/HPSN Combinations With and Without Overlayers of CVD $\rm Si_3N_4$

The purpose of Task II of this program is to evaluate the effect of thermal cycling to 1200 and 1370 $^{\rm O}{\rm C}$ in air on the integrity of the RSSN/HPSN combinations, in particular the effect of silica formation within the RSSN layer on its ability to absorb energy during ballistic impact. In addition, the hot gas erosion characteristics of the RSSN layers at 1200 and 1370 $^{\rm O}{\rm C}$ in a Mach 0.8 gas stream are to be evaluated, both with and without a thin overlayer of chemically vapor deposited (CVD) Si₃N₄. The CVD Si₃N₄ overlayer is being investigated as a possible oxidation and erosion resistant barrier for the RSSN/HPSN combinations.

4.5.1 Thermal Cycling of $\mathrm{Si}_{3}\mathrm{N}_{4}$ Control Samples

Ballistic impact samples of both NC-132 and NCX-34 $\mathrm{Si}_3\mathrm{N}_4$ were subjected to 75 thermal cycles between ~150 to $1200^{\circ}\mathrm{C}$ and ~200 to $1370^{\circ}\mathrm{C}$ in air. An exposure cycle consisted of heating to either 1200 or $1370^{\circ}\mathrm{C}$ in ~15 min, holding at temperature for 40 min, and then cooling to the minimum temperature in a cold air blast for 10 min. After thermal cycling, the samples were inspected visually and analyzed for weight gain and, by X-ray diffraction, for the formation of surface oxide phases. They were then tested in ballistic impact at a sample temperature of 20 and $1370^{\circ}\mathrm{C}$.

The weight gain and oxide formation data for the thermally cycled ballistic impact control samples of NC-132 and NCX-34 Si₃N₄ are given in Table XVII. For both temperatures, the oxide layer formed on the NC-132 Si3N, was much thicker than that formed on the NCX-34 Si3N4, as expected from previous oxidation data for these two materials. Figure 34 shows the surface of the NCX-34 Si₂N₁ (left) and the NC-132 Si₃N₄ (right) samples after the 75 cycle, 1370°C exposure. There was no evidence of the low temperature oxidation problem previously noted for the NCX-34 Si₃N₄ occurring during cycling of this material to either 1200 or 1370°C. The weight gain for the NC-132 Si₃N₄ was approximately three times that of the NCX-34 Si_3N_4 at $1370^{\circ}C$ and approximately 70% higher at $1200^{\circ}C$. At 1370° C, the oxide formed on the NCX-34 $Si_{3}N_{4}$ was entirely crystalline, as determined from X-ray analysis, consisting of elongated Y2Si2O7 crystals with a small amount of SiO₂ (cristobalite). The oxide layer formed on the NC-132 $\mathrm{Si}_{3}\mathrm{N}_{4}$ was a mixture of a glassy silicate phase, SiO_{2} (cristobalite), and MgSiO_{3} (clinoenstatite). At 1200°C, the predominant surface oxide phase formed on both materials was SiO2 (cristobalite) with small amounts of what appears to be the X₁ phase of Y₂SiO₅ forming on the NCX-34 and small amounts of Si₂N₂O plus an unidentified phase on the NC-132 Si₃N₄.

The results of ballistic impact tests at RT and $1370^{\circ}\mathrm{C}$ on thermally cycled $\mathrm{Si}_{3}\mathrm{N}_{4}$ substrates control samples are given in Table XVIII and compared to values for as-received controls. Within statistical scatter, there does not appear to be any significant effect of thermal cycling on the ballistic impact properties of either NC-132 or NCX-34 $\mathrm{Si}_{3}\mathrm{N}_{4}$. Both materials exhibit somewhat better RT ballistic impact properties and somewhat poorer $1370^{\circ}\mathrm{C}$ impact properties after thermal cycling, except for the NCX-34 material cycled to $1200^{\circ}\mathrm{C}$ and tested at $1370^{\circ}\mathrm{C}$. In general, the $1200^{\circ}\mathrm{C}$ cycling gives higher ballistic impact results than the $1370^{\circ}\mathrm{C}$ cycle, for both NC-132 and NCX-34 $\mathrm{Si}_{3}\mathrm{N}_{4}$. The fracture mode for the materials was not changed by the thermal cycling exposure.

4.5.2 Thermal Cycling of RSSN/HPSN Combinations

Samples of both NC-132 and NCX-34 $\rm Si_3N_4$ with -200 RSSN layers containing ~25 vol % Si were subjected to thermal cycling tests between 150 and $1200^{\circ}\mathrm{C}$ and between 200 and $1370^{\circ}\mathrm{C}$. Samples of NC-132 with -325 RSSN layers have also been thermally cycled. From weight gain measurements of cycled samples, it was determined that the -200 RSSN layers cycled 75 times to $1200^{\circ}\mathrm{C}$ gained ~115 mg while the -325 RSSN layers gained ~110 mg. The -200 RSSN layers cycled to $1370^{\circ}\mathrm{C}$ gained ~150 mg while the -325 RSSN layers gained ~130 mg. No difference in weight gain was noted between RSSN layers on NC-132 or NCX-34 substrates. X-ray analysis of the cycled RSSN layers revealed that the oxide product consisted entirely of α -cristobalite (SiO₂). The amount of residual Si in the cycled layers was essentially unchanged as calculated from X-ray analysis, so that the silica that was formed resulted from the reaction of oxygen with the

 α and β Si $_3N_4$, not with the Si. This would be expected, since the residual Si exists in the interior of $\beta\text{-Si}_3N_4$ particles. Photomicrographs of the cycled RSSN layers revealed that the silica almost completely filled the void space that previously existed between Si $_3N_4$ particles, as shown in Fig. 35 for a -200 RSSN layer cycled 75 times to 1370°C. At high magnifications, as shown in Fig. 35b, it can be seen that the Si particles appear to be oxidizing somewhat along grain boundaries.

The results of RT and 1370°C ballistic impact rests on the RSSN/HPSN combinations, both as-fabricated and cycled 75 times to 1200°C and 1370°C are shown in Table XIX. Only the energy and velocity necessary to fracture the hot-pressed substrate are shown in Table XIX. From these results, it can be seen that the ballistic impact resistance of -200 Si RSSN layers on both NC-132 and NCX-34 Si₃N₄ substrates, tested either at RT or 1370°C , either increases or stays the same after 75 thermal cycles to 1200°C or 1370°C . The -325 RSSN layers on NC-132 Si₃N₄ also showed no decrease in RT impact resistance after thermal cycling.

From the tests conducted on samples cycled to either 1200 or 1370° C, it is apparent that the formation of α -cristobalite in the interior and on the surface of the porous RSSN layers does not cause degradation of the RSSN layer and in most instances has a beneficial effect on its impact resistance. The silica forms predominantly at the expense of the Si_3N_4 , not the residual Si, and thus does not reduce the amount of residual Si below the apparently critical value of 20 vol % necessary for optimum impact resistance. The silica also appears to withstand the high to low cristobalite transformation that occurs when the sample is cooled through the $200-275^{\circ}$ C range, at least without cracking or delaminating the RSSN layer.

4.5.3 Thermal Cycling of RSSN/HPSN Combinations with CVD $\mathrm{Si}_3\mathrm{N}_4$ or SiC Overlayers

As described in the following section on Mach 0.8 gas erosion testing, the formation of a protective CVD $\rm Si_3N_4$ overlayer on the RSSN layers was not possible due to the residual Si present in the optimized RSSN layers interfering with the deposition process at the usual deposition temperatures of $1400-1450^{\circ}\rm C$. A fully nitrided RSSN layer was shown to be amenable to CVD $\rm Si_3N_4$ deposition at $1450^{\circ}\rm C$ with subsequent thermal cycling of the sample to $1370^{\circ}\rm C$ showing no appreciable oxidation of the RSSN layer. However, the impact resistance of the fully nitrided RSSN layers is about one-third of layers with 20 vol % residual Si so that if oxidation protection of the RSSN layer by a CVD $\rm Si_3N_4$ overlayer is desired, a compromise in impact resistance must be made.

Since CVD SiC can be deposited at a much lower temperature than CVD Si $_3$ N $_4$, it was decided to investigate RSSN layers with overlayers of CVD SiC. Even though the thermal expansion coefficient of SiC (~4.5 x 10^{-6} /°C) is somewhat higher than that of Si $_3$ N $_4$ (~3.1 x 10^{-6} /°C), thus causing residual tensile stresses in the SiC upon cooling from the deposition temperature (1120°C), it was thought that a very thin but continuous CVD SiC overlayer could be protective of the RSSN layers.

CVD SiC deposition was carried out at 1120°C using a mixture of methane and hydrogen saturated with methyldichlorosilane. The first samples of NC-132 with -200 Si layers were coated with CVD SiC of ~6 mils (.15 mm) in thickness. On cooling from deposition, the CVD SiC coatings cracked but were still very adherent to the RSSN layer. The corncob appearance of the CVD SiC and the cracks formed can be seen in Fig. 36. Upon thermal cycling to 1370°C, the SiC overlayer tended to spall off, thus not offering any protection from oxidation. The sample shown in Fig. 37 completed 21 cycles to 1370°C with the coating starting to spall after ~10 cycles. Due to the spallation of the coating, no weight gain data could be taken but it can be assumed that the RSSN layer contained considerable silica.

The CVD deposition parameters were changed to obtain a thinner, finer grained SiC coating. Subsequent samples exhibited coatings of 0.5 to 1.5 mils (12-36 μ) in thickness. Figure 38 shows the CVD SiC surface of a sample of NC-132 with -200 RSSN layer, with the thickness of the CVD SiC coating being ~1 mil (25 μ). As can be seen in this figure, cracks are still in evidence in some areas of the coating. It was found that all coatings of thickness 1 mil (25 μ) or greater contained cracks, whereas thinner SiC coatings were crack free.

A total of ten NC-132 ballistic impact samples with -200 RSSN layers (20% Si) were coated with 0.5-1.5 mils (12-36µ) of CVD SiC and then subjected to 75 thermal cycles to 1370°C. These samples along with nonthermal cycled samples with CVD SiC overlayers, were then tested at RT and 1370°C in ballistic impact. The weight gain and oxide formation data for the thermally cycled samples is shown in Table XX. As can be seen from Table XX, the weight gain of the samples with CVD SiC overlayers is somewhat higher than NC-132 Si₃N₄ substrates and substantially lower than the RSSN/HPSN combinations with no CVD SiC overlayer. The actual values of weight gain for the samples with CVD SiC overlayers ranged from 36 mg for thin (~12µ) CVD SiC, with no cracks evident, to 70 mg for a thicker (~36µ) CVD SiC that exhibited cracking similar to that shown in Fig. 38. A fairly thick silica layer formed on the CVD SiC during cycling which, on cooling, exhibited some cracking as shown in Fig. 39. From the weight gain data and from X-ray diffraction analysis it is apparent that while some internal oxidation of the RSSN layer is occurring, it is much reduced by the presence of the CVD SiC overlayer.

The ballistic impact resistance of as-fabricated and thermally cycled samples with CVD SiC overlayers was determined at RT and 1370°C, is shown in Table XXI. The only difference noted between those samples with CVD SiC coatings and those without was a slightly lower impact resistance for the thermally cycled samples with CVD overlayers. This is likely due to the relatively lesser amount of internal oxidation within the RSSN layer for the samples with CVD SiC overlayers. Table XXII summarizes all of the ballistic impact data obtained on thermally cycled samples, both with and without CVD SiC overlayers.

4.5.4 Mach 0.8 Hot Gas Erosion Testing

In order to determine the effect of a simulated gas turbine environment on the erosion and oxidation characteristics of the RSSN energy absorbing surface layers, samples of NC-132 and NCX-34 Si $_3\mathrm{N}_4$, both with and without -200 and -325 RSSN layers, were subjected to Mach 0.8 hot gas erosion testing for 5 hrs at sample surface temperatures of 1200 and 1370°C. The samples tested at 1200°C were approximately 1.92 x 1.23 x 0.64 cm (0.75 x 0.50 x 0.25 in) in size with the largest face positioned at a 30° angle to the direction of hot gas flow. Samples run at 1370°C had a substrate thickness of 0.28 cm (0.15 in). Sample temperatures were monitored by a continually recording optical pyrometer. Samples of -325 and -200 RSSN layers with CVD Si $_3\mathrm{N}_4$ or SiC overlayers were also tested in erosion at 1200 and 1370°C.

4.5.4.1 Erosion Testing of Si₃N₄ Controls

Both NC-132 and NCX-34 Si_3N_4 controls were tested in erosion at 1200 and 1370°C. The two control samples of hot-pressed Si₃N₄ tested at 1200°C did not exhibit any detectable weight change or surface recession. X-ray analysis of the exposed surfaces indicated no detectable oxide formation during the 5 hr test. Erosion testing at 1370°C for 5 hrs on NC-132 and NCX-34 Si₃N₄ controls, however, did produce measurable surface recession. Somewhat surprisingly, the NCX-34 Si₃N₄ sample eroded considerably more (~25 μ) than the NC-132 Si₃N₄ (~2.5 μ). The NC-132 Si₃N₄ sample gained a slight amount of weight (0.1 mg) while the NCX-34 Si₃N₄ sample lost weight (3.5 mg). Both samples exhibited a very thin oxide scale on the surface (predominantly \alpha-cristobalite from X-ray diffraction measurements) which would tend to increase the weight of the sample; however, in the case of the NCX-34 Si_3N_4 this weight gain was more than offset by weight loss due to material erosion. Figures 40 and 41 show the eroded surfaces of the NC-132 and NCX-34 samples tested at 1370°C. While both samples exhibit a rather rough oxidized surface, the NC-132 appears to have a glassy, bubbly oxide layer while the NCX-34 has a more crystalline but substantially rougher surface.

4.5.4.2 Erosion Testing of RSSN/HPSN Combinations

Samples of NC-132 and NCX-34 $\mathrm{Si_3N_4}$ with -200 and -325 RSSN layers, containing ~25 vol % Si, were erosion tested for 5 hrs at 1200 and $1370^{\circ}\mathrm{C}$. The RSSN layers tested at $1200^{\circ}\mathrm{C}$ did not exhibit measurable surface recession, but did exhibit substantial weight gains of ~20 mg. RSSN samples tested at $1370^{\circ}\mathrm{C}$ exhibited a slight amount of surface recession (~8 μ) (Fig. 42) but a somewhat lower weight gain of ~12 mg; the latter due to less of the substrate surface being covered with the RSSN layer. From X-ray analysis, a substantial amount of $\mathrm{Si0_2}$ (α -cristobalite) was present on the surface and in the interior of the RSSN layers tested at both 1200 and $1370^{\circ}\mathrm{C}$. Figure 43 shows the -325 and -200 RSSN layers tested at $1370^{\circ}\mathrm{C}$, along with the NC-132 and NCX-34 $\mathrm{Si_3N_4}$ controls tested at the same temperature. No difference in erosion behavior between the -325 and -200 RSSN layers can be observed. Figure 44 shows the erosion surface of the -200 RSSN layers tested at 1200 and $1370^{\circ}\mathrm{C}$, with the $1370^{\circ}\mathrm{C}$ sample exhibiting a much rougher surface oxide scale. Table XXIII gives the complete results of the Mach 0.8 hot gas erosion tests on the $\mathrm{Si_3N_4}$ controls and RSSN layers.

4.5.4.3 Erosion Testing of RSSN Layers with CVD Si_3N_4 and SiC Overlayers

TOTAL STATE OF THE PARTY OF THE

While the hot gas erosion resistance of RSSN layers containing 25 vol % Si at 1200 and 1370°C is quite good, as far as surface recession is concerned, the large amount of oxide formation may be detrimental during very long time exposures. It would thus be desirable to have a CVD coating system that would protect the RSSN layer from oxidation. CVD Si $_3$ N $_4$ coatings deposited at the usual deposition temperatures of $1400-1450^{\circ}$ C, using a mixture of SiF $_4$ + NH $_3$, can be extremely protective of fully nitrided RSSN material; however, the presence of residual Si for optimum impact resistance in the RSSN layers studied under this program has prevented the formation of a successful CVD Si $_3$ N $_4$ coating applied at $1400-1450^{\circ}$ C.

A sample of NCX-34 $\mathrm{Si_3N_4}$ with a -200 RSSN layer that had been coated with a .005 cm (2 mil) layer of CVD $\mathrm{Si_3N_4}$ at a deposition temperature of $1450^{\circ}\mathrm{C}$ (Fig. 45), was run for 5 hrs in the hot gas erosion rig at $1200^{\circ}\mathrm{C}$. The sample exhibited no surface recession after the run, but did gain a considerable amount of weight (22 mg), indicating that the CVD $\mathrm{Si_3N_4}$ layer did not completely cover the RSSN surface. X-ray analysis indicated that the CVD $\mathrm{Si_3N_4}$ layer was 100% α - $\mathrm{Si_3N_4}$, both before and after erosion testing. From optical microscope examination, this coating covered the RSSN quite well except for occasional pinholes. The pinholes appeared to be forming over residual Si particles in the RSSN layer. It was apparent that the residual Si was melting and/or vaporizing during the CVD process and preventing complete coverage of the RSSN surface.

The CVD process parameters were changed such that the chamber temperature would not exceed 1400°C , thus preventing Si meltout. The CVD Si $_3\text{N}_4$ coating formed under these conditions appeared to be continuous when viewed in crosssection (Fig. 46), but still contained a few pinholes located over residual Si particles. While the Si did not appear to be melting, the Si vapor pressure must be high enough to cause Si vaporization, thus preventing complete Si $_3\text{N}_4$ deposition. A sample of NC-132 Si $_3\text{N}_4$ with a -325 RSSN layer, covered with a CVD Si $_3\text{N}_4$ coating of 2 mils (50 μ) that was deposited at 1400 °C, was run for 5 hrs at 1370°C in the hot gas erosion rig. The sample gained a considerable amount of weight (33 mg), indicating that oxygen was penetrating into the RSSN layer through pinholes in the CVD coating, but exhibited no measurable surface recession and no oxide formation on the CVD Si $_3\text{N}_4$ surface. It is apparent that the erosion resistance of an RSSN layer with a CVD Si $_3\text{N}_4$ coating would be excellent if a pinhole-free coating could be deposited.

Since a protective CVD $\rm Si_3N_4$ overlayer could not be obtained, CVD $\rm SiC$ layers were deposited at $\rm 1120^{\circ}C$ on erosion samples of NC-132 and NCX-34 with -200 RSSN layers. The CVD $\rm SiC$ layers were ~1.5 mils ($\rm 36\,\mu$) in thickness. The results of erosion tests at 1200 and 1370 C (see Table XXIII) showed that these overlayers were very resistant to surface recession and relatively good in oxidation protection. Compared to the CVD $\rm Si_3N_4$ overlayers, the CVD $\rm SiC$ overlayed samples gained only 6 mg (vs 22 mg for $\rm Si_3N_4$) at 1200 C and only 2.5 mg (vs 33 mg) at 1370 C. The slight amount of $\rm SiO_2$ that formed on the surface of the CVD $\rm SiC$ at 1370 C was evidently sealing the surface cracks in the $\rm SiC$, thus not allowing significant internal oxidation of the RSSN layer to occur. Figure 47 shows the cross-section of a -200 RSSN layer with a CVD $\rm SiC$ overlayer both before and after a 5 hr, $\rm 1370^{\circ}C$ erosion test. The erosion test has roughened the CVD $\rm SiC$ overlayer somewhat, but other wise there exists no significant difference in the two samples.

Interestingly, a rather dense transition zone exists under the CVD SiC overlayer and can be seen in both samples in Fig. 47. From electron microprobe examination, this transition zone consists of residual Si particles surrounded by a rather dense matrix that contains Si, N, C, and some O. The reactant gases during the early stages of the CVD process are evidently reacting with the α -Si₃N₄ whisker matrix forming either a mixture of SiC and Si₃N₄ with some O₂ contamination or some compound of the four elements. If a compound is forming, X-ray analysis has not been able to identify it.

Bend tests conducted on as-nitrided -200 RSSN layers on NCX-34 $\rm Si_3N_4$ and identical samples after the application of a CVD SiC overlayer showed a decrease in RT 4-pt bend strength for the samples with CVD SiC overlayers compared to those without. The samples without CVD SiC overlayers averaged 590 MPa (86 ksi) when the -200 RSSN layer was tested in tension, while those with CVD SiC

overlayers averaged 421 MPa (61 ksi). The fracture origin of the samples with CVD SiC overlayers was invariably located close to the RSSN/HPSN interface near the corner of the sample where the dense CVD SiC/RSSN transition zone came into contact with the HPSN substrate, as shown in Fig. 48. The dense transition zone is evidently providing a crack path at the corners of the sample where it is in contact with the HPSN substrate. Samples tested that had 0.25 mm (10 mils) ground off each side so as to remove the transition zone that is in contact with the HPSN substrate did not exhibit severe strength degradation, averaging 540 MPa (78 ksi) in strength.

In an actual component of dense $\mathrm{Si}_3\mathrm{N}_4$ with an RSSN energy absorbing surface layer overlaid by a CVD SiC coating, it would be likely that the CVD SiC/RSSN transition zone would not come into contact with the dense $\mathrm{Si}_3\mathrm{N}_4$ component. If it did, the part could probably be designed so that the transition zone region in contact with the dense $\mathrm{Si}_3\mathrm{N}_4$ would not be a highly stressed area.

V. CONCLUSIONS

The major conclusions that can be reached from work done on this program to improve the toughness (impact resistance) of hot-pressed Si_3N_4 are as follows:

- 1. The ballistic impact resistance and bend strength at RT of Norton Co. NCX-34 hot-pressed $\mathrm{Si}_3\mathrm{N}_4$ is substantially higher than that of NC-132 $\mathrm{Si}_3\mathrm{N}_4$. At $1370^{\circ}\mathrm{C}$ the ballistic impact resistance of the two materials is approximately equal.
- 2. Certain lots of NCX-34 $\mathrm{Si}_3\mathrm{N}_4$ with $\mathrm{Y}_2\mathrm{O}_3$ additive, including all three billets used for this program, exhibit catastrophic oxidation properties in the temperature range of $700\text{-}1000^{\circ}\mathrm{C}$. The cause of this phenomenon is not fully understood and must be further investigated in order to fully utilize the potential of $\mathrm{Si}_3\mathrm{N}_4$ with $\mathrm{Y}_2\mathrm{O}_3$ additive.
- 3. Reaction sintered Si $_3N_4$ (RSSN) surface layers on either NC-132 or NCX-34 Si $_3N_4$ substrates cause a severe (~50%) drop in strength of the substrate when the nitriding is carried out in pure flowing N_2 , but only a minimal drop in strength when the Si powder layer is nitrided in a 96% $N_2/4\%$ H $_2$ mixture. The reason for the strength degradation appears to be connected with the difference in microstructure between RSSN layers nitrided in pure N_2 and in N_2/H_2 mixtures. Large, interconnected β -Si $_3N_4$ particles are formed when nitriding is done in pure N_2 whereas the β -Si $_3N_4$ particles formed in N_2/H_2 mixtures are always separated from each other and from the substrate by an α -Si $_3N_4$ whisker mat. Thus, no large stress-concentrating flaws (β -Si $_3N_4$ particles) are bonded directly to the HPSN surface and cracks initiating in the RSSN layer cannot propagate directly through β -Si $_3N_4$ grains and into the HPSN substrate.
- 4. Ballistic impact tests at RT and 1370°C on NC-132 and NCX-34 $\text{Si}_{3}\text{N}_{4}$ substrates with 1 mm thick RSSN layers fabricated from either -325 mesh, -200 mesh, or -100, +200 mesh Si powder indicated that fully nitrided layers (i.e., no residual Si) result in only modest (50-100%) improvement in impact resistance over HPSN control values.
- 5. To obtain optimum impact resistance on the order to 600-700% improvement over control values, the nitriding schedule must result in at least 20 vol % residual Si remaining within the RSSN layer. The residual Si is apparently absorbing a great deal of energy as it is crushed and fractured by the ballistic projectile.

- 6. For a smooth surface finish and a relatively dense (~30% porosity) microstructure, either -325 or -200 mesh Si powder nitrided in $\rm N_2/H_2$ mixtures to a residual Si content of 20-25 vol % is preferred over the rather coarse -100, +200 Si powder previously used. Control of the residual Si content with the finer powders is more difficult, however.
- 7. Thermal cycling 75 times between $150-200^{\circ}\text{C}$ to either 1200 or 1370°C does not adversely affect the ballistic impact resistance of either NC-132 or NCX-34 Si₃N₄ control samples nor does it affect the impact improvement of -325 and -200 RSSN layers (25 vol % Si) on HPSN substrates. A large amount of silica (cristobalite) is formed within the RSSN layers during cycling, but this did not affect the RSSN/HPSN bonding or the ability of the RSSN layers to absorb energy during impact since the silica forms primarily at the expense of the α -Si₃N₄ within the RSSN layers and thus does not reduce the Si content below the critical 20 vol % level.
- 8. Attempts to form an oxidation and erosion protective CVD $\rm Si_3N_4$ overlayer on RSSN layers containing residual Si were not successful due to the high Si vapor pressure at the deposition temperature (1400-1450°C) interfering with the deposition process and causing pinhole formation over residual Si particles.
- 9. CVD SiC overlayers were successfully deposited at 1120°C on RSSN layers containing Si and, while cracking of the SiC was often a problem, crack-free coatings were deposited and, on thermal cycling to 1370°C, did offer substantial oxidation protection and no decrease in ballistic impact properties, although a bend strength decrease was noted due to crack propagation through a dense transition zone under the CVD SiC coating.
- 10. Mach 0.8, 5 hr, hot gas erosion testing at sample temperatures of 1200°C and 1370°C on NC-132 and NCX-34 $\text{Si}_{3}\text{N}_{4}$ controls showed that no surface recession or weight change occurred at 1200°C , while at 1370°C a very slight surface recession (2.5 μ) and weight gain (+0.1 mg) was observed for NC-132 $\text{Si}_{3}\text{N}_{4}$ and a rather large surface recession (25 μ) and weight loss (-3.5 mg) for NCX-34 $\text{Si}_{3}\text{N}_{4}$. For the -325 and -200 RSSN layers with 25 vol % Si, no surface recession was detected at 1200°C while a small surface recession (~8 μ) was detected at 1370°C . A substantial weight gain was observed at both temperatures due to internal oxidation of the RSSN layer.
- 11. Erosion tests of -200 RSSN layers (25 vol % Si) with 36 μ (1.5 mil) overlayers of CVD SiC showed no surface recession at 1200 or 1370 $^{\circ}$ C and very small weight gains. It is felt that an optimized CVD SiC overlayer could offer excellent oxidation and erosion protection for RSSN energy absorbing surface layers on dense Si₃N₄ substrates.

12. From the results of various research programs carried out during the past six years that have been concerned with improving the impact resistance of $\mathrm{Si}_3\mathrm{N}_4$ through the use of compressive surface layers (Refs. 4-6) or energy absorbing surface layers (Refs. 1,7-10), the system of R.S. $\mathrm{Si}_3\mathrm{N}_4$ surface layers on dense $\mathrm{Si}_3\mathrm{N}_4$, investigated during this contract, appears to be the only practical system investigated thus far for potential use as an energy absorbing surface layer on dense $\mathrm{Si}_3\mathrm{N}_4$ used as a high temperature structural ceramic. While the RSSN surface layers do tend to degrade the inherent bend strength of the dense $\mathrm{Si}_3\mathrm{N}_4$ substrate somewhat, and they do tend to oxidize internally in high temperature environments, these do not appear to be limiting factors in the application of the RSSN energy absorbing surface layer concept.

REFERENCES

- Rhodes, W. H. and R. M. Cannon, Jr.: "High Temperature Compounds for Turbine Vanes", AVCO Systems Division Report, NASA CR-134531, Contract NAS3-16757 (Jan. 1974) and NASA CR-120966, Contract NAS3-14333 (Sept. 1972).
- 2. Brennar, J. J.: "Development of Fiber Reinforced Ceramic Matrix Composites", UTRC Report N911647-3, Contract N62269-73-C-2068 (Jan. 1974).
- 3. Brennan, J. J.: "Development of Fiber Reinforced Ceramic Matrix Composites", UTRC Report R911848-1, Contract N62269-74-C-0268 (Feb. 1975).
- 4. Platts, D. R., H. P. Kirchner and R. M. Gruver: "Strengthening Oxidation Resistant Materials for Gas Turbine Applications", Ceramic Finishing Co. Report, NASA CR-121002, Contract NAS3-15561 (Sept. 1972).
- 5. Gruver, R. M., D. R. Platts and H. P. Kirchner: "Strengthening Silicon Carbide by Quenching", Bull. Amer. Ceram. Soc. 53 (7) 524-527 (July 1974).
- 6. Kirchner, H. P.: "Strengthening of Oxidation Resistant Materials for Gas Turbine Applications", Ceramic Finishing Co. Report, NASA CR-134661, Contract NAS3-16788 (June 1974).
- 7. Kirchner, H. P. and J. Seretsky: "Improving Impact Resistance by Energy Absorbing Surface Layers", Ceramic Finishing Co. Report, NASA CR-134644, Contract NAS3-17765 (March 1974).
- 8. Palm, J. A.: "Improved Toughness of Silicon Carbide", General Electric Co., NASA CR-134921, Nov. 1975.
- 9. Palm, J. A.: "Improved Toughness of Silicon Carbide", NASA CR-134990, Final Report on Contract LAS3-17832 (Jan. 1976).
- 10. Brennan, J. J. and C.O. Hulse: "Development of $\rm Si_3N_4$ and SiC of Improved Toughness", NASA CR-135306, Final Report on Contract NAS3-19731, Oct. 25, 1977.
- 11. Gazza, G. E., H. Knoch, and G. D. Quinn: "Hot-Pressed Si₃N₄ with Improved Thermal Stability", Bull. Am. Cer. Soc., Vol. 57, No. 11, Nov. 1978, pp 1059-1060.
- 12. Brennan, J. J.: "Evaluation of Tantalum Fiber Reinforced Si_3N_4 ", NADC-75207-30, Final Report on Contract N62269-76-C-0104, April 1, 1977.

- 13. Gazzara, C. P. and D. R. Messier: "Quantitative Determination of Phase Content of Silicon Nitride by X-ray Diffraction Analysis", AMMRC Report TR75-4, Feb. 1975.
- 14. Lindley, M. W., D. P. Elias, B. F. Jones, and K. C. Pitman: "The Influence of Hydrogen in the Nitriding Gas on the Strength, Structure and Composition of Reaction-Sintered Si₃N₄", J. Matls. Sci. 14 (1979) pp 70-85.

Table I Spectrochemical Analysis of Norton NC-132 and NCX-34 $\mathrm{Si}_3\mathrm{N}_4$ Impurity Content

NC-132 Si ₃ N ₄	Element	Wt % Present
$\rho = 3.25 \text{ gms/cc}$		
	A1	0.10
	Fe	0.15
	Mg	0.35
	W	3.00
	Cr,Co,Cu, Mn,Ti,Ca,Na	<0.01 each
NCX-34 Si ₃ N ₄		
$\rho = 3.35 \text{ gm/scc}$		
	Y	7.15*
	Fe	0.20
	A1	0.20
	Mn	0.05
	W	2.90*
	Ca	0.10
	B,Mg,Ti	<0.01 each

*Determined by atomic absorption

Sample		Grain Size (µ)	
	Max.	Mean	Min.
NC-132	2.4	0.80	<0.15
NCX-34	2.7	0.88	<0.15

Table III

Impurity Content of Si Powders (w/o)

Powder	Fe	<u>A1</u>	Mn	Mg	Pb	Cr	<u>Ti</u>	Ca
-325 Si (98%)	.7	.2	.3	<.01	.01	.1	.03	.1
-325 Si (99.6%)	.05	.1	<.01	<.01	.1	<.01	<.01	.05
-200 Si (98.5%)	. 4	. 2	.1	<.01	.02	.05	<.01	.1
-100,+200 Si (98.5%)	.3	.2	.03	<.01	.02	<.01	.02	.1

 $\label{eq:Table IV} \mbox{BET (N$_2$) Surface Area Analysis of Si Powders}$

Powder Sample	Surface Area (m ² /g)
-325 Si (99.6% purity)	7.2
-325 Si (98% purity)	2.7
-200 Si (98.5% purity)	0.77

Table V $RT \ and \ 1370\,^{\circ}C \ Ballistic \ Impact \ Properties \ of \ NCX-34 \ and \ NC-132 \\ Si_{3}N_{4} \ Controls \ Using \ 0.34 \ gm \ (4.4 \ mm) \ Hardened \\ Chrome-Steel \ Projectile$

Sample No.	Temp (°C)	Impact m/sec	Velocity ft/sec	Impact joules	Energy ft-lbs	Comments
NCX-34-BI-1	RT	130	425	2.8	2.1	Tensile Failure
-2		130	425	2.8	2.1	11 11
-3	"	127	415	2.7	2.0	Hertzian Failure
-4	11	127	415	2.7	2.0	Tensile Failure
-5	u .	134	440	3.0	2.2	11 11
	Avgs	130	425	2.8	$\frac{2.2}{2.1}$	
-6	1370	134	440	3.0	2.2	Tensile Failure
-7	11	117	385	2.3	1.7	Fracture Origin
-8		127	415	2.7	2.0	Uncertain
- 9	11	117	385	2.3	1.7	"
-10		117	385	2.3	1.7	H.
	Avgs	$\frac{117}{122}$	400	$\frac{2.3}{2.6}$	$\frac{1.7}{1.9}$	
NC-132 Averages	RT	105	345	1.9	1.4	Predominantly Hertzian Failure
п	1370	128	420	2.8	2.1	50-50 Hertzian & Tensile Failure

Table VI $RT\ and\ 1370^{o}C\ Ballistic\ Impact\ Properties\ of\ NCX-34\ Si_{3}N_{4}$ with 1 mm Thick RSSN Layer, Nitrided 60 hrs at 1375 ^{o}C

Layer	Temp. °C	Impact m/sec	Velocity ft/sec	Impact joules	Energy ft-lbs	Comments
-325 Si	RT	191	630	6.2	4.6	Layer destroyed, no damage to substrate
n	"	230	755	9.1	6.7	$\mathrm{Si}_{3}\mathrm{N}_{4}$ substrate fractured, tensile failure
n	"	246	810	10.5	7.7	u
"	1370	169	555	4.9	3.6	Layer destroyed, no damage to substrate
"	"	191	630	6.2	4.6	$\mathrm{Si}_{3}\mathrm{N}_{4}$ substrate fractured, tensile failure
-100,+200 Si*	RT	169	555	4.9	3.6	Layer destroyed, no damage to substrate
n	II .	191	630	6.2	4.6	$\mathrm{Si}_{3}\mathrm{N}_{4}$ substrate fractured, tensile failure
"	1370	152	500	3.7	2.7	Layer destroyed, no damage to substrate
"	п	169	555	4.9	3.6	$\mathrm{Si}_{3}\mathrm{N}_{4}$ substrate fractured, origin uncertain

^{* &}lt;5 v/o Si unreacted

Table VII

RT Ballistic Impact Properties of NC-132 and NCX-34 Si₃N₄ with 1 mm Thick RSSN Layer (-100,+200 Si),

25-30 v/o Unreacted Si Nitrided 24 hrs at 1375°C

Substrate					
Material	Impact	Velocity	Impact	Energy	Comments
	m/sec	ft/sec	joules	ft-1bs	
NC-132 Si ₃ N ₄	191	630	6.2	4.6	Two-thirds of layer retained, no damage to substrate
II	212	695	7.6	5.6	Layer destroyed, no damage to substrate
"	230	755	9.1	6.7	H .
"	246	810	10.5	7.7	$\mathrm{Si}_{3}\mathrm{N}_{4}$ substrate fractured, Hertzian failure
NCX-34 S1 ₃ N ₄	191	630	6.2	4.6	Half of layer retained, no damage to substrate
"	212	695	7.6	5.6	TI .
"	230	755	9.1	6.7	Layer destroyed, no damage to substrate
II .	246	810	10.5	7.7	п
п	260	850	11.4	8.4	п
п	271	890	12.5	9.2	$\mathrm{Si}_{3}\mathrm{N}_{4}$ substrate fractured, tensile failure

Table VIII RT Ballistic Impact Tests of RSSN Layers, 1 mm Thick, on NCX-34 $\rm Si_3N_4$ (Nitrided to 1375 $^{\rm O}$ C, 8 hrs)

Layer	Impact V	Velocity ft/sec	Impact joules	Energy ft-1bs	Comments
-325 Si	169	555	4.9	3.6	2/3 of layer destroyed, no damage to substrate
"	191	630	6.2	4.6	$\mathrm{Si}_{3}\mathrm{N}_{4}$ substrate fractured, tensile failure
-100,+200 Si*	260	850	11.4	8.4	layer destroyed, no damage to substrate
"	272	890	12.5	9.2	$\mathrm{Si}_{3}\mathrm{N}_{4}$ substrate fractured, tensile failure
11	282	925	13.6	10.0	n ,

^{* 60} v/o Si unreacted

Table IX RT Ballistic Impact Properties of NC-132 and NCX-34 $\rm Si_3N_4$ with 1 mm Thick RSSN Layers, Nitrided 1 hr at 1375 $^{\rm O}$ C, $\rm N_2$

Substrate Material	Layer	Impact V	elocity ft/sec	Impact	Energy ft-lbs	Comments
				100103	10-108	Comments
NC-132	-200 Si*	230	755	9.1	6.7	Layer destroyed only at point of impact, no damage to substrate
"	"	260	850	11.4	8.4	Two-thirds of layer re- tained, no damage to substrate
п	п	282	925	13.6	10.0	Layer destroyed, no damage to substrate
u	u	300	980	15.4	11.4	$\mathrm{Si}_{3}\mathrm{N}_{4}$ substrate fractured, Hertzian failure
NCX-34	n	300	980	15.4	11.4	Half of layer destroyed, no damage to substrate
NC-132	-325 Si**	282	925	13.6	10.0	Layer destroyed, no damage to substrate
"	u .	300	980	15.4	11.4	$\mathrm{Si}_{3}\mathrm{N}_{4}$ substrate fractured, Hertzian failure
NCX-34	"	300	980	15.4	11.4	Layer destroyed, no damage to substrate

^{* 30} v/o unreacted Si

^{** 20} v/o unreacted Si

Table X RT Ballistic Impact Properties of NC-132 and NCX-34 Si $_3$ N $_4$ with 1 mm Thick RSSN Layers, Nitrided 1 hr at 1375 $^{\rm O}$ C in 96% N $_2$ /4% H $_2$

Substrate		Impact	Velocity	Impact	Energy	
Material	Layer	m/sec	ft/sec	joules	ft-1bs	Comments
NC-132	-200 Si*	260	850	11.4	8.4	Layer destroyed only at point of impact, no damage to substrate
н	"	282	925	13.6	10.0	Half of layer destroyed, no damage to substrate
n	11	300	980	15.4	11.4	$\mathrm{Si_3N_4}$ substrate fractured, tensile failure
NCX-34	-200 Si*	300	980	15.4	11.4	Layer destroyed only at point of impact, no damage to substrate
11	"	315	1045	17.2	12.7	$\mathrm{Si}_{3}\mathrm{N}_{4}$ substrate fractured, Hertzian failure
NCX-34	-325 Si**	191	630	6.2	4.6	Layer destroyed, no damage to substrate
"	"	230	755	9.1	6.7	$\mathrm{Si}_{3}\mathrm{N}_{4}$ substrate fractured, Hertzian failure
п	"	260	850	11.4	8.4	$\mathrm{Si}_{3}\mathrm{N}_{4}$ substrate fractured, tensile failure

^{* 21} v/o unreacted Si

^{** 5} v/o unreacted Si

Table XI RT Ballistic Impact Properties of NCX-34 Si $_3$ N $_4$ with 1 mm Thick RSSN Layers, Nitrided for Various Times at 1375 C in 96% N $_2$ /4% H $_2$

Layer	Time at 1375°C (Vol % Si)	Impact m/sec	Velocity ft/sec	Impact joules	Energy ft-lbs	Comments
-325 Si	30 min (20% Si)	343	1125	19.7	14.5	Layer destroyed, no damage to substrate
"	1 hr (5% Si)	191	630	6.2	4.6	"
•	п	230	755	9.1	6.7	$\mathrm{Si}_{3}\mathrm{N}_{4}$ substrate fractured, Hertzian failure
-200 Si	30 min (25% Si)	300	9 80	15.4	11.4	2/3 of layer des- troyed, no damage to substrate
"	"	315	1045	17.2	12.7	$\mathrm{Si}_{3}\mathrm{N}_{4}$ substrate fractured, Hertzian failure
"	1 hr (21% Si)	300	980	15.4	11.4	Layer destroyed only at point of impact, no damage to substrate
"	"	315	1045	17.2	12.7	$\mathrm{Si}_{3}\mathrm{N}_{4}$ substrate fractured, Hertzian failure
"	1½ hrs (14% Si)	191	630	6.2	4.6	Layer destroyed, no damage to substrate
"	"	230	755	9.1	6.7	$\mathrm{Si}_{3}\mathrm{N}_{4}$ substrate fractured, tensile failure
"	2 hrs (6% Si)	191	630	6.2	4.6	Layer destroyed, no damage to substrate
"	"	230	755	9.1	6.7	$\mathrm{Si}_{3}\mathrm{N}_{4}$ substrate fractured, tensile failure

Table XII $RT\ and\ 1370^{\circ}C\ Ballistic\ Impact\ Properties\ of\ NC-132\ and\ NCX-34$ $Si_3N_4\ with\ 1\ mm\ Thick\ RSSN\ Layers\ Containing\ 5\ vol\ \%\ Residual\ Si$ $(1\ hr\ at\ 1375^{\circ}C\ ,\ N_2/H_2)$

Layer	Substrate	Temp.	Impact m/sec	Velocity ft/sec	Impact joules	Energy ft-1bs	Comments
-325 Si	NC-132	RT	169	555	4.9	3.6	Layer destroyed, no damage to substrate
"	"	RT	191	630	6.2	4.6	$\mathrm{Si_{3}N_{4}}$ substrate fractured, tensile failure
"	"	1370°C	230	755	9.1	6.7	Layer destroyed, no damage to substrate
"	u	1370°C	260	850	11.4	8.4	$\mathrm{Si}_{3}\mathrm{N}_{4}$ substrate fractured, tensile failure
"	NCX-34	RT	191	630	6.2	4.6	Layer destroyed, no damage to substrate
"	"	RT	230	755	9.1	6.7	$\mathrm{Si}_{3}\mathrm{N}_{4}$ substrate fractured, Hertzian failure
"	"	1370°C	152	500	3.7	2.7	Layer virtually in- tact, no damage to substrate
"	"	1370°C	169	555	4.9	3.6	$\mathrm{Si}_{3}\mathrm{N}_{4}$ substrate fractured, fracture origin uncertain

Table XIII $1370^{\circ}\text{C Ballistic Impact Properties of NC-132 and NCX-34}$ Si $_3\text{N}_4$ with 1 mm Thick RSSN Layers Containing ~25 vol % Residual Si (30 min at 1375°C , N_2/H_2)

Substrate	Layer	Impact V	Velocity ft/sec	Impact E		Comments
NC-132	-200 Si	300	9 80	15.4	11.4	Layer destroyed, no damage to substrate
"	"	315	1045	17.2	12.7	$\mathrm{Si}_{3}\mathrm{N}_{4}$ substrate fractured, Hertzian failure
NCX-34	"	260	850	11.4	8.4	Layer destroyed only at point of impact, no damage to substrate
n	u	282	925	13.6	10.0	$\mathrm{Si}_{3}\mathrm{N}_{4}$ substrate fractured, fracture origin uncertain
NC-132	-325 Si	315	1045	17.2	12.7	2/3 of layer destroyed, no damage to substrate
11	11	336	1100	19.0	14.0	$\mathrm{Si}_{3}\mathrm{N}_{4}$ substrate fractured, Hertzian failure
NCX-34	11	260	850	11.4	8.4	2/3 of layer destroyed, no damage to substrate
"	11	282	925	13.6	10.0	$\mathrm{Si}_{3}\mathrm{N}_{4}$ substrate fractured, fracture origin uncertain

Table XIV RT Ballistic Impact Condition Needed to Fracture NC-132 Si $_3$ N $_4$ with Varying Thickness RSSN Layer (25 vol % Si)

	Layer	Impact	Velocity	Impact Energy		
Layer	Thickness	m/sec	ft/sec	Joules	ft-lbs	
-200 Si	1.0 mm	300	9 80	15.4	11.4	
-200 Si	0.64 mm	282	925	13.6	10.0	
-200 Si	0.50 mm	260	850	11.4	8.4	
-200 Si	0.25 mm	212	695	7.6	5.6	
None	-	105	345	1.9	1.4	

Table XV ${\rm RT~4-pt~Bend~Tests~on~NC-132~and~NCX-34~Si}_3{\rm N}_4,$ With and Without 1 mm Thick RSSN Surface Layers

Layer	Nitriding Treatment	Modulus of Rupture	- MPa (ksi) NCX-34
None*	None	662 (96)	848 (123)
-325 Si**	Ar, 1150°C, 20 hrs	695 (101)	827 (120)
-325 Si**	Ar, 1150°C, 20 hrs + N ₂ , 1250°C, 24 hrs	627 (91)	690 (100)
-325 S1**	Ar, 1150°C, 20 hrs + N ₂ , 1250°C, 24 hrs + N ₂ , 1375°C, 24 hrs	327 (47.5)	414 (60) 700 (102) poor bond
-100, +200 Si**	11	405 (58.7)	462 (67)
-325 Si*	Standard Ar, 1150° C, 20 hrs + N ₂ , 1250° C, 24 hrs + N ₂ , 1375° C, 60 hrs	324 (47)	414 (60) 710 (103) poor bond
-100, +200 Si*	"	338 (49)	427 (62)
None*	II .	785 (114)	725 (105)

^{*}Average of 10 tests **Average of 5 tests

Table XVI RT 4-pt Bend Strength of NC-132 and NCX-34 $\rm Si_3N_4$ with Well Bonded RSSN Layers Nitrided in $\rm N_2/H_2$ to 1375 $^{\circ}\rm C$

Substrate	Layer	Vol % Si	Modulus of Rupture* MPa ksi
NC-132	-325 Si (98%)	<5%	632 91.6
"	-325 Si (99.6%)	<5%	361 52.3
"	-100,+200 Si (98.5%)	5-10%	338 49.0
"	-325 or -200 Si (98%)	20-25%	503 73.0
NCX-34	-325 Si (98%)	<5%	640 92.8
	-325 Si (99.6%)	<5%	78.2 (well-bonded) 708 103.0 (poorly-bonded)
	-100,+200 Si (98.5%)	5-10%	513 74.5
	-325 or -200 Si (98%)	20-25%	572 83.0

^{*}Average of three tests

Table XVII

Weight Gain and Oxide Formation on NC-132 and NCX-34 $\rm Si_3N_4$ Controls After 75 Cycles from 200 \rightarrow 1370 $^{\rm O}$ C and 150 \rightarrow 1200 $^{\rm O}$ C

Substrate	Thermocycle	Wt Gain-mg*	Oxide Formation
NCX-34	200 → 1370°C	8.2(0.30 mg/cm ²)	$Y_2Si_2O_7 + SiO_2$
NC-132	II .	$23(0.85 \text{ mg/cm}^2)$	MgSiO ₃ + SiO ₂ + glass
NCX-34	150 → 1200°C	4(0.15 mg/cm ²)	SiO_2 (major) + Y_2SiO_5 (minor)
NC-132	11	6.7(0.25 mg/cm ²)	SiO_2 (major) + Si_2N_2O (minor) + unidentified minor phase

^{*}average of six samples

Table XVIII

RT and 1370 $^{\rm O}{\rm C}$ Ballistic Impact Properties of NC-132 and NCX-34 ${\rm Si}_3{\rm N}_4$ Control Samples, As-received and After 75 Thermal Cycles to $1200^{\rm O}{\rm C}$ and $1370^{\rm O}{\rm C}$

Comments	Predominantly Hertzian Failure " Hertzian & Tensile Failure "	Predominantly Tensile Failure	Fracture Origins Uncertain "
Impact Energy* oules ft-lbs	1.4 1.7 1.5 2.1 1.9	2.1 2.4 2.3	1.9 2.2 1.6
Impact	1.9 2.3 2.0 2.8 2.6	2.8 3.3	2.6 3.0 2.2
Impact Velocity m/sec ft/sec	345 385 365 420 405	425 458 444	400 438 378
Impact m/sec	105 117 111 128 123 120	130 140 135	122 133 115
Test Temp.	RT " 1370°C	RT "	1370°C "
Cycle	None $150 + 1200^{\circ}C$ $200 + 1370^{\circ}C$ None $150 + 1200^{\circ}C$ $200 + 1370^{\circ}C$	None 150 \rightarrow 1200°C 200 \rightarrow 1370°C	None $150 \div 1200^{\circ} \text{C}$ $200 \div 1370^{\circ} \text{C}$
Sample	NC-132	NCX-34	z z z

*average of 5 tests

Table XIX

Comments	Hertzian failure	Indeterminate failur	Hertzian fallure Tensile failure	Hertzian failure	: :	Tensile failure	Hertzian failure	No fracture	Herrzian failure		
Energy ft-1bs	12.7	10.0	12.7	11.4	11.4						14.0
Impact Energy joules ft-lbs	17.2	13.6	17.2	15.4	15.4	15.4	15.4	19.0	17.2	19.0	19.0
Impact Velocity m/sec ft/sec	1045	925	980	9.80	980	08 6	086	1100	1045	1100	1100
Impact m/sec	315	282	315	300	300	300	300	>336	315	336	336
Test Temp.	RT	1370°C		RT			=		1370°C		=
Treatment Test Temp.	cycled to 1200 C "		cycled to 1370° C "		cycled to 1200° C " cycled to 1370° C "						cycled to 1370°C "
		none			cycled to 1200° C cycled to 1370° C	none	cycled to 1200 C				

The Report of the Party of the

re

Table XX

Weight Gain and Oxide Formation for NC-132 $\rm Si_3N_4$ with -200 RSSN Surface Layers after 75 Cycles from $200^{\circ}\text{C}\!\!\to\!\!1370^{\circ}\text{C}$, Both With and Without CVD SiC Overlayers

Substrate	Layer	Overlayer	Thermocycle	Wt Gain (mg)	Oxide Formation
NC-132	none	none	200→1370°C	23	$MgSiO_3 + SiO_2 + glass$
"	-200 Si	none	"	153	α -cristobalite (SiO $_2$)
"		CVD SiC	11	52	n

Table XXI

Ballistic Impact Energy Necessary to Fracture NC-132 $\mathrm{Si}_3\mathrm{N}_4$ With 1 mm Thick RSSN Layers (20-25 vol % Si), As-fabricated and After 75 Cycles from $200 \div 1370^{\mathrm{O}}\mathrm{C}$ Both With and Without CVD SiC Overlayers

Energy ft-lbs	11.4	15.4 11.4	14.0	12.7
Impact Energy joules ft-lbs	15.4 11.4	15.4	19.0 14.0	17.2 12.7
Impact Velocity m/sec ft/sec	086	9 80	1100	1045
Impact m/sec	300	300	336	315
Test Temp	RT	:	:	:
Treatment	none	none	cycled to $1370^{\circ}\mathrm{C}$	
Overlayer	none	CVD Sic	none	CVD SiC
Layer	-200 Si			
Substrate	NC-132			

Note: Values for 1370°C test results are comparable

Table XXII

Ballistic Impact Properties of Thermally
Cycled* RSSN/HPSN Combinations

Layer	Thermal Cycle	Fracture	for Substrate (joules) NCX-34 Si ₃ N ₄ RT 1370°C
		<u>KI</u> 1370 C	K1 1370 C
None	None	1.9 2.8	2.8 2.6
"	75 cycles, 150→1200°C	2.3 2.6	3.3 3.0
"	75 cycles, 200→1370°C	2.0 2.4	3.1 2.2
-200 Si(20-25 v/o Si)	None	15.4 -	17.2 13.6
u	75 cycles, 150→1200°C	15.4 -	19.0 15.4
u	75 cycl e s, 200→1370°C	19.0 -	19.0 17.2
-200 Si + CVD SiC	None	15.4 -	
II.	75 cycles, 200→1370°C	17.2 -	
			-
-325 Si(20-25 v/o Si)	None	15.4 17.2	
"	75 cycles, 150→1200°C	15.4 19.0	
а	75 cycles, 200→1370°C	17.2 19.0	


 $[*]Cycle = 15 \min heatup + 40 \min hold + 10 \min cold air blast cool$

Table XXIII


Mach 0.8, 5 hr, Hot Gas Erosion Testing of NC-132 and NCX-34 Si3N4 Controls and RSSN Surface Layers

Surface X-ray Analysis	β -Si $_3$ N $_4$	=	α -Si $_3N_4$, β -Si $_3N_4$, Si, Si0 $_2$		α -Si $_3$ N $_4$	β-SiC	$\beta-\mathrm{Si}_3\mathrm{N}_4+\mathrm{SiO}_2$ (minor)	=	α -Si $_3N_{\mu}$, β -Si $_3N_{\mu}$, Si, Si0 $_2$		α -Si ₃ N ₄ + SiO ₂ (Minor)	β -SiC + SiO ₂ (minor)
Wt. Change	0	0	+21.2 mg	+17.1 mg	+22.0 mg	e 0.0 mg	+0.1 mg	-3.5 mg	+12.4 mg	+12.2 mg	+33 mg	+2.5 mg
Surface Recession	Not Detectable	Ξ	Ξ	:	:	Ξ	0.1 mils (2.5μ)	1.0 mils (25μ)	0.3 mils (8µ)	0.3 mils (8µ)	Not Detectable	=
Test Temp.	1200°C	:	=	:	:	:	1370°C	E	:	:	:	:
Layer	None	None	-200 Si	-325 Si	-200 Si + CVD Si $_3$ N $_4$	-200 Si + CVD SiC	None	None	-325 Si	-200 Si	$-325 \text{ Si} + \text{CVD Si}_3\text{N}_4$	-200 Si + CVD SiC
Substrate	NCX-34	NC-132	NCX-34	NCX-34	NCX-34	NC-132	NC-132	NCX-34	NC-132	NC-132	NC-132	NCX-34

MICROSTRUCTURE OF NC-132 (a) AND NCX-34 (b) HOT-PRESSED Si₃N₄ (TEM REPLICA)




NCX-34 Si₃N₄ SAMPLE FROM BILLET F 338355 SHOWING MICROCRACKS ENHANCED BY ZYGLO PENETRANT



61

${\tt NCX-34\,Si_3N_4\,OXIDATION\,STUDY}$

100 HR 930°C




62


78-10-259-4

FIG. 17


NCX $-34~Si_3N_4$ (BILLET F338355) AGED IN AIR AT 730 $^{\rm o}$ C FOR 48 HRS




STEPS IN FABRICATION OF HPSN/RSSN BALLISTIC IMPACT SAMPLES













INTERFACE BETWEEN -100, +200 RSSN LAYER AND NCX $-34~{\rm Si}_3{\rm N}_4$, NITRIDED TO $1375^{\rm O}{\rm C}$, $60~{\rm HRS}$, ${\rm N}_2$



RSSN LAYER (-100, +200 Si) NITRIDED TO 1375°C, 24 HRS, N₂ (25-30 V/O UNREACTED Si)



RSSN LAYER (-100, +200 Si) NITRIDED TO 1375°C, 8 HRS, N₂ (60 V/O UNREACTED Si)



RSSN LAYER (-325 Si) NITRIDED TO 1375°C, 8 HRS, N₂ (Si COMPLETELY NITRIDED)




RSSN LAYER (-100, +200 Si) NITRIDED TO 1300°C, 8 HRS, N₂ (10 V/O OF Si CONVERTED TO Si₃N₄)




50μ

BALLISTIC IMPACT SAMPLE OF NC-132 Si₃N₄ WITH -200 RSSN LAYER AFTER 9.1 JOULE IMPACT



0.5cm


RSSN LAYER (-200 Si) NITRIDED TO 1375°C, 1 HR, 96% N $_2$ /4% H $_2$ (21 V/O UNREACTED Si)



RSSN LAYER (-325 Si) NITRIDED TO 1375°C, 1 HR, 96% N $_2$ /4% H $_2$ (5 V/O UNREACTED Si)




BALLISTIC IMPACT SAMPLE OF NCX-34 Si₃N₄ WITH -200 RSSN LAYER (21 V/O Si) AFTER 15.4 JOULE IMPACT



BALLISTIC IMPACT SAMPLE OF NCX $-34~\mathrm{Si_3N_4}$ WITH $-200~\mathrm{RSSN}$ LAYER (21 V/O Si) AFTER 17.2 JOULE IMPACT




BALLISTIC IMPACT SPECIMEN OF NCX $-34~Si_3N_4~WITH -325~RSSN~LAYER~(5~V/O~Si)$ IMPACTED AT 1370°C, 169 M/SEC (4.9 JOULES)



0.5cm





FRACTURE SURFACE OF BALLISTIC IMPACT SPECIMEN SHOWN IN FIG. 16




71


Ballistic Impact Properties of NC-132 Si₃N₄ with RSSN Energy Absorbing Surface Layers









IMPACT SURFACE OF A STEEL SPHERE AFTER 130 M/SEC (2.8 JOULES) IMPACT WITH NCX $-34~{
m Si}_3{
m N}_4$ CONTROL







IMPACT SURFACE OF A STEEL SPHERE AFTER 230 M/SEC (9.1 JOULES) IMPACT WITH A -200 RSSN LAYER (6 V/O Si) ON NCX-34 Si $_3$ N $_4$




IMPACT SURFACE OF A STEEL SPHERE AFTER 260 M/SEC (11.4 JOULES) IMPACT WITH A-200 RSSN LAYER (21 V/O Si) ON NCX-34 Si $_3$ N $_4$




POINT OF IMPACT THROUGH A-200 RSSN LAYER DOWN TO THE HPSN SUBSTRATE FOR A STEEL SPHERE TRAVELING AT 300M/SEC



FRACTURE SURFACE OF NC-132 Si₃N₄ WITH -325 Si LAYER (NITRIDED AT MAXIMUM TEMP. OF 1250°C FOR 24 HRS.)




FRACTURE SURFACE OF NC-132 Si₃N₄ WITH -325 Si LAYER (NITRIDED AT MAXIMUM TEMP. OF 1375°C FOR 24 HRS.)




R79-914364-12 FIG. 26

FRACTURE SURFACE OF POORLY BONDED RSSN LAYER ($-325~{\rm Si},\,98\%$) ON NCX $-34~{\rm Si}_3{\rm N}_4$, NITRIDED TO 1375°C, 60 HRS, N₂






FRACTURE SURFACE OF STRONGLY BONDED RSSN LAYER (-100, +200 Si) ON NCX-34 Si₃N₄, NITRIDED TO 1375°C, 60 HRS, N₂



OVERALL VIEW

800μ



ORIGIN AREA


100μ

FRACTURE ORIGIN OF NCX-34 Si $_3$ N $_4$ WITH LOOSE -100, +200 Si PARTICLES ON THE SURFACE, NITRIDED TO 1375 $^{\rm o}$ C, 60 HRS, N $_2$






FRACTURE SURFACE OF -325 Si (98%) RSSN LAYER ON NC-132 Si $_3$ N $_4$, NITRIDED IN 96% N $_2$ / 4% H $_2$ TO 1375° C, 60 HRS



OVERALL VIEW


625µ



ORIGIN AREA


100μ

FRACTURE SURFACE OF $-325~\rm Si$ (98%) RSSN LAYER ON NCX $-34~\rm Si_3N_4$, NITRIDED IN 96% N $_2/4\%$ H $_2$ TO 1375°C, 60 HRS



OVERALL VIEW






ORIGIN AREA

100μ




FRACTURE SURFACE OF -325 Si (98%) RSSN LAYER ON NC-132 Si₃N₄, NITRIDED IN N₂ TO 1375°C, 60 HRS



OVERALL VIEW

8004




ORIGIN AREA


90

79-01-72-1

79-09-139-3


Effect of RSSN Layer on R.T. 4-Pt. Bend Strength of NC-132 Si₃N₄







THE RESERVE TO SERVE TO SERVE

Effect of RSSN Layer on R.T. 4-Pt. Bend Strength of NCX-34 Si₃N₄






NCX-34 $\rm Si_3N_4$ (LEFT) AND NC-132 $\rm Si_3N_4$ (RIGHT) SAMPLES EXPOSED FOR 75 CYCLES FROM 200°C TO 1370°C,




RSSN LAYER $(-200~{\rm Si})$ ON NC $-132~{\rm Si}_3{\rm N}_4$ AFTER 75 CYCLES TO 1370°C




94

THICK (0.15MM) CVD Si C ON - 200 RSSN/HPSN BALLISTIC IMPACT SAMPLE




50μ

THERMALLY CYCLED (21 CYCLES TO 1370°C) SAMPLE OF -200 RSSN ON NC-132 Si₃N₄ WITH THICK (0.15 MM) CVD SiC OVERLAYER





0.5 CM


THIN (25 μ), FINE GRAINED CVD Si C OVERLAYER ON -200 RSSN




OXIDIZED SURFACE OF CVD SiC OVERLAYER AFTER 75 CYCLES TO 1370°C.








NC-132 Si₃N₄ WITH -200 RSSN LAYER (25% Si) AFTER 1370°C, 5 HR. MACH 0.8 EROSION TEST




HOT GAS EROSION TEST SAMPLES AFTER 5 HRS. AT 1370°C



0.5 CM

102

SEM OF -200 RSSN EROSION SAMPLES TESTED AT (A) 1200°C, 5 HRS., AND (B) 1370°C, 5 HRS.




SURFACE OF CVD si_3N_4 OVERLAYER ON A -200 RSSN/HPSN EROSION SAMPLE.




104


CROSS-SECTION OF A CVD Si₃N₄ COATING DEPOSITED AT 1400°C ON -200 RSSN LAYER




CROSS—SECTION OF A-200 RSSN LAYER WITH A CVD SiC OVERLAYER BEFORE (A) AND AFTER (B) A 5 HR, 1370°C EROSION TEST



FRACTURE SURFACE OF -200 RSSN/HPSN COMBINATION WITH CVD SiC OVERLAYER





DATE